

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Oct-2019 11:20	SWL only.	14.21
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	11-Oct-2019 11:04	SWL only.	56.79
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	11-Oct-2019 10:54	SWL only.	54.228
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	11-Oct-2019 10:38	SWL only.	52.5
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Oct-2019 08:26	SWL only.	13.96
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Oct-2019 14:10	Low flow pump. Clear sample. No particles in sample. Slight sulphur odour.	6.02
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Oct-2019 13:20	Low flow pump. Clear sample. No particles in sample. Nil odour.	16.17
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Oct-2019 14:59	Low flow pump. Clear sample. No particles in sample. Slight sulphur odour.	8.32
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 11:50	Low flow pump. Clear sample. No particles in sample. Nil odour.	18.01
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 11:13	Low flow pump. Clear sample. No particles in sample. Nil odour.	28.44
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Oct-2019 09:05	Low flow pump. Clear sample. No particles in sample. Nil odour.	31.5
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Oct-2019 13:15	Low flow pump. Clear sample. No particles in sample. Nil odour.	21.97
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 14:40	Low flow pump. Clear sample. No particles in sample. Sulphur odour.	12.84
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 10:48	SWL only.	55.84
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	11-Oct-2019 10:43	SWL only.	38.045
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Oct-2019 10:06	Dry. Dry at approx. 17m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Oct-2019 10:09	SWL only.	65.025
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	11-Oct-2019 12:18	SWL only.	45.69
MB3 RDH1097	Monitoring bore 3 - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	11-Oct-2019 13:29	SWL only.	36.915
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Oct-2019 12:41	SWL only.	21.09
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	4-Oct-2019 08:51	SWL only.	59.29
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 13:16	SWL only.	35.931
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	9-Oct-2019 07:22	SWL only.	62.51
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 11:52	SWL only.	37.285
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	8-Oct-2019 08:12	Low flow pump. Clear sample. No particles in sample. Nil odour.	20.33
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 12:46	Low flow pump. Clear sample. No particles in sample. Nil odour. Duplicate collected as 251_QAQCD01.	16.86
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Oct-2019 06:44	Bailor. Clear sample. Organic particles in sample. Nil odour.	3.87
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Oct-2019 10:35	Low flow pump. Clear sample. No particles in sample. Nil odour.	16.36
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Oct-2019 09:47	Low flow pump. Clear sample. No particles in sample. Nil odour.	19.6
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Oct-2019 11:27	Low flow pump. Clear sample. No particles in sample. Nil odour.	23.91

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Oct-2019 12:19	Bailor. Slightly turbid sample. Light brown in colour. Fine white particles in sample. Organic odour.	19.92
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Oct-2019 08:11	SWL only.	49.61
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Oct-2019 08:21	SWL only.	15.17
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Oct-2019 13:25	Low flow pump. Clear sample. No particles in sample. Nil odour.	32.5
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 10:24	SWL only.	58.825
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-Oct-2019 09:55	SWL only. SWL double checked and confirmed.	68.4
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 08:15	SWL only.	182.17
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Oct-2019 07:44	SWL only.	162.8
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 10:18	Sampled from Tap. Clear sample. No particles in sample. Nil odour. New tap installed. Pump running at time of collection.	29.65
R1	Regional 1 - Landholder monitoring bore located on Yarran property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Oct-2019 07:58	SWL only.	41.52
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Oct-2019 11:06	SWL only.	18.3
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 11:40	SWL only.	52.19
R12	Regional 12 - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	14-Oct-2019 09:09	SWL only.	25.16
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 15:31	SWL only.	16.17
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Oct-2019 08:39	SWL only.	12.3
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	9-Oct-2019 07:05	SWL only.	20.16
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Oct-2019 08:47	SWL only.	15.28
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	4-Oct-2019 09:14	SWL only.	38.57
R3	Regional 3 Landholder Monitoring bore located on Banyula property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Oct-2019 10:31	SWL only.	30.33
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 11:28	SWL only.	32.17
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	4-Oct-2019 15:56	SWL only.	14.4
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 15:13	SWL only.	28.45
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Oct-2019 08:37	SWL only.	37.34
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Oct-2019 08:34	SWL only.	60.03
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 09:32	SWL only.	37.16
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Oct-2019 09:50	SWL only.	31.71
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	11-Oct-2019 06:35	Bailor. Cloudy sample. Light grey in colour. Fine white particles in sample. Slight earthy odour.	5.78
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	10-Oct-2019 16:14	Bailor. Clear sample. Organic particles in sample. Sulphur odour. Bailed 6L. EC double checked and confirmed.	3.6
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	10-Oct-2019 15:48	Bailor. Clear sample. Organic particles in sample. Nil odour. Bailed 6L. EC double checked and confirmed.	2.01

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Oct-2019 16:22	Dry. TD 1.8m.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	14-Oct-2019 09:22	SWL only.	30.98
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	9-Oct-2019 15:19	SWL only.	23.93
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Oct-2019 08:40	Low flow pump. Clear sample. No particles in sample. Earthy odour.	27.4
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Oct-2019 09:33	Bailor. Turbid Sample. Grey in colour. Fine white particles in sample. Earthy odour. SWL double checked and confirmed. Bailed 7L. After 7L bailer started coming up with mud. (Close to bottom).	40.66
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Oct-2019 10:57	Bailor. Cloudy sample. Slight grey in colour. Fine white particles in sample. Earthy odour. Insufficient water to pump. Bailed 12L.	28.86
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Oct-2019 11:32	Low flow pump. Clear sample. Fine white particles in sample. Earthy odour.	37.02
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Oct-2019 06:46	Low flow pump. Clear sample. No particles in sample. Earthy odour.	17.92
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Oct-2019 07:40	Low flow pump. Clear sample. No particles in sample. Earthy odour.	17.79
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Oct-2019 09:17	Low flow pump. Clear sample. No particles in sample. Earthy odour. SWL double checked and confirmed.	25.12
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Oct-2019 10:04	Low flow pump. Clear sample. No particles in sample. Earthy odour.	28.31
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Oct-2019 10:34	Low flow pump. Clear sample. No particles in sample. Nil odour.	23.97