

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2019 09:17	SWL only.	151.13
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	4-Nov-2019 14:30	SWL only.	56.784
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	4-Nov-2019 14:21	SWL only.	54.19
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	4-Nov-2019 14:42	SWL only.	52.564
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2019 11:35	Pipe obstructing access for dipper tape. No SWL.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2019 14:02	SWL only.	22.7
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2019 11:28	SWL only.	142.4
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	6-Nov-2019 12:42	SWL only.	13.96
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2019 08:31	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	6.02
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Nov-2019 09:09	Low Flow Pump. Clear sample. No particles in sample. Slight Sulphur odour.	16.165
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:52	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	8.41
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	6-Nov-2019 08:30	SWL only.	14.23
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 11:48	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	18.055
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 10:42	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	28.835
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 08:55	Low Flow Pump. Slightly cloudy. No particles in sample. Nil odour.	31.546
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 07:04	Low Flow Pump. Sample clear. No particles in sample. Nil odour.	22.29
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 15:37	Low Flow Pump. Clear sample. No particles in sample. Slight Sulphur odour.	12.95
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	4-Nov-2019 14:51	SWL only.	27.61
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	4-Nov-2019 14:47	SWL only. Tape stopped at 27.610	
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:01	Dry. Dry at approx. 17m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:00	SWL only. Bend in bore. No sample collected. SWL only.	65.26
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2019 00:01	Not Scheduled.	
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	6-Nov-2019 11:43	SWL only.	35.993
MB3 RDH1097	Monitoring bore 3 - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	6-Nov-2019 12:31	SWL only.	36.984
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	6-Nov-2019 12:40	SWL only.	21.131
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	4-Nov-2019 12:29	SWL only.	59.25
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2019 13:05	SWL only.	37.265
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 08:14	Low Flow Pump. Sample clear. No particles in sample. Nil odour.	20.725
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 07:29	Low Flow Pump. Clear sample. No particles in sample. Nil odour. Duplicate collected. 251_QAQCD01.	16.97
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2019 11:02	New road in next to bore. Bore bent. (photos taken). Still able to get SWL but PVC bent inside stopping bailer going down. Ben Westerberg notified.	3.95

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 13:28	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	16.315
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 12:39	Low Flow Pump. Sample slightly cloudy. No particles in sample. Nil odour.	19.64
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 14:20	Low Flow Pump. Cloudy sample. Yellow/Brown colour. No particles in sample. Nil odour.	23.88
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 14:59	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	19.92
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2019 12:21	SWL only. SWL double checked and confirmed.	49.31
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2019 12:36	SWL only.	15.19
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 08:39	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	32.57
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	4-Nov-2019 13:47	SWL only.	57.74
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 09:38	Sampled from Tap. Sample clear. No particles in sample. Nil odour. Pump running.	30.085
R1	Regional 1 - Landholder monitoring bore located on Yarran property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Nov-2019 13:09	SWL only. SWL double checked and confirmed.	42.025
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Nov-2019 10:16	SWL only.	18.203
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 09:32	SWL only.	52.21
R12	Regional 12 - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	6-Nov-2019 11:29	SWL only.	25.17
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2019 14:54	SWL only.	36.12
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 07:52	SWL only.	16.23
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2019 12:58	SWL only.	12.29
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	8-Nov-2019 13:31	SWL only.	20.15
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2019 11:57	SWL only.	53.714
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2019 13:41	SWL only.	15.28
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	4-Nov-2019 12:12	SWL only.	38.53
R3	Regional 3 Landholder Monitoring bore located on Banyula property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Nov-2019 10:46	SWL only.	30.385
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 09:47	SWL only.	32.194
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	9-Nov-2019 07:01	SWL only.	14.42
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 07:18	SWL only.	28.45
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Nov-2019 15:19	SWL only.	37.34
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	4-Nov-2019 15:24	SWL only.	59.95

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 11:42	SWL only.	37.145
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	4-Nov-2019 11:27	SWL only.	31.71
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	6-Nov-2019 10:47	Bailed. Clear sample. Fine white particles in sample. Nil odour. Bailed 6L. New road beside bore.	5.84
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:22	Bailed. Slightly turbid sample. Fine Black particles settled at bottom of sample. Organic odour.	3.92
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	6-Nov-2019 09:59	Bailed. No particles in sample. Bailed 6L. EC double checked and confirmed.	2.16
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:09	SWL only. Tape stopped at 1.8m approx.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	6-Nov-2019 12:11	SWL only.	30.945
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	6-Nov-2019 10:38	SWL only.	23.995
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	6-Nov-2019 07:22	Low Flow Pump. Clear sample. No particles in sample. Organic (earthy) odour.	27.37
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Nov-2019 08:15	Bailed. Turbid sample. Brown in colour. Course white particles in sample. Organic (earthy) odour. Insufficient water to pump. Bailed 12L. Large amount of white mud on bailor.	40.82
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 15:12	Bailed. Clear sample. No particles in sample. Organic (earthy) odour. Bailed 12L than sampled.	28.83
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 13:22	Low Flow Pump. Clear sample. No particles in sample. Organic (earthy) odour.	36.97
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 09:39	Low Flow Pump. Cloudy sample. No particles in sample. Organic (earthy) odour.	17.97
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 10:11	Low Flow Pump. Clear sample. No particles in sample. Organic (earthy) odour.	17.81
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Nov-2019 11:33	Low Flow Pump. Clear sample. No particles in sample. Organic (earthy) odour.	25.28
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2019 12:33	Low Flow Pump. Clear sample. No particles in sample. Organic (earthy) odour.	28.45
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2019 09:58	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	24.37