

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 11:55	SWL only. Unable to get bailor or pump down bore. Unable to collect sample.	155.206
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	17-Feb-2020 08:20	Low Flow Pump. Turbid sample. Brown. Fine Brown. Nil odour. Outer monument cap missing. Pump hit bottom at 60.5 m. Pumped at 60 m.	56.8
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	17-Feb-2020 09:07	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Nil odour. Nil damage.	54.121
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	9-Feb-2020 11:39	SWL only. Slightly turbid sample. Very light brown No particles in sample. Nil odour. Nil damage. Tape beeping at 35.22 - may be a leak in casing. Pump reset at 12:00.	52.35
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 12:18	SWL only. Unable to sample due to pipe obstruction in bore. No sample collected.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	17-Feb-2020 11:47	Low Flow Pump. Slightly turbid sample. Very light brown. Organic particles in sample. Brown. Nil odour. Nil damage.	22.752
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 12:20	SWL only. Multiple attempts to bail, unable to obtain sufficient water.	145.126
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	10-Feb-2020 08:46	Low Flow Pump. Clear sample. Fine Black particles at bottom of sample, very few. Nil odour.	14.065
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 09:21	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	5.209
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Feb-2020 09:51	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	16.142
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 08:37	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	7.725
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Feb-2020 07:25	Low Flow Pump. Clear sample. Fine black particles in sample. Nil odour.	14.24
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 11:42	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	18.23
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 10:36	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	29.41
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Feb-2020 08:35	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	31.55
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	3-Feb-2020 07:39	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	22.88
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	17-Feb-2020 10:22	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Nil odour. Nil damage. QAQCD04 taken.	13.402
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	9-Feb-2020 13:15	Dry. Dip tape stopped at 27.7 m.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	9-Feb-2020 12:48	Low Flow Pump. Cloudy sample. Light grey - white No particles in sample. Burnt odour. Nil damage.	38.49
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 11:11	Dry. Dip tape stopped at 17.101 m	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Feb-2020 11:05	Could not sample. Casing bent so pump or bailer could not be deployed. No sample taken.	65.168
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 13:10	Bailed. Insufficient water to get sample.	163.31
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	11-Feb-2020 06:59	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	36.194
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	17-Feb-2020 13:08	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Nil odour. Nil damage.	45.788
MB3 RDH1097	Monitoring bore 3 - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	11-Feb-2020 11:58	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	36.981
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Feb-2020 14:13	Low Flow Pump. Clear sample. Very light grey. Fine Black. Sulphur odour. Burnt coal smell.	21.131
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Feb-2020 07:31	Low Flow Pump. Cloudy sample. Very light brown No particles in sample. Nil odour. Nil damage. 63 m.	59.26

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Feb-2020 10:31	Low Flow Pump. Slightly turbid sample. Yellow tint. Fine Very few black particles Slight Sulphur odour.	36.03
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	10-Feb-2020 15:40	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	62.55
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Feb-2020 06:46	Low Flow Pump. Turbid sample. Yellow brown. No particles in sample. Nil odour. Nil damage.	37.224
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Feb-2020 07:29	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	21.3
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-Feb-2020 10:48	Low Flow Pump. Clear sample. No particles in sample. Nil odour. Duplicate collected as 251_QAQCD01.	17.37
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 12:25	SWL only. Bore PVC squeezed about 1.5m down bore. Unable to get bailer or pump down. SWL only. No sample collected.	4.03
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	3-Feb-2020 09:35	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	16.41
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	3-Feb-2020 10:32	Low Flow Pump. Clear sample. No particles in sample. Nil odour. Duplicate collected as QAQCD02.	19.87
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	3-Feb-2020 09:03	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	23.62
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	3-Feb-2020 08:37	Bailed. Slightly turbid sample. Light grey in colour. Organic particles in sample. Nil odour. Bailed 12L.	20.01
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Feb-2020 12:01	Low Flow Pump. Clear sample. Slight yellow tint. Course Very few, orange/brown at bottom. Nil odour. SWL double checked and confirmed.	48.961
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Feb-2020 07:46	SWL only. Pump stops at 38m. Sample very slightly cloudy. Nil odour. Nil particles.	15.245
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Feb-2020 10:09	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	32.61
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	17-Feb-2020 09:51	SWL only. Plinth and monument badly damaged.	57.459
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 07:04	Bailed. Clear sample. Clear sample. Organic particles in sample. Brown, black. Burnt odour. Nil damage. Could not get close access due to boggy ground d. Bailed 6 lt then sampled.	68.541
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 10:32	Attempted to bail multiple times, unable to gain a sample.	182.082
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Feb-2020 09:56	SWL only. Bailed 4 times - no sample. Too much grit in the water, bailer won't seal for the extended lift. Suggest hydra sleeve.	165.418
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 09:45	Grab Sample. Clear sample. No particles in sample. Slight Sulphur odour. Sampled from tap. Pump running at time of collection.	30.66
R1	Regional 1 - Landholder monitoring bore located on Yarran property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Feb-2020 11:52	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Nil damage.	41.498
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	17-Feb-2020 16:41	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Nil odour. Nil damage.	18.338
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	3-Feb-2020 14:13	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Missing outer cap.	52.361
R12	Regional 12 - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	11-Feb-2020 08:06	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	25.119
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	11-Feb-2020 08:54	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Nil damage.	35.968
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	20-Feb-2020 09:26	Low Flow Pump. Clear sample. Nil colour. No particles in sample. Nil odour.	16.15

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Feb-2020 09:35	Low Flow Pump. Cloudy sample. Yellow/Brown No particles in sample. Nil odour.	12.282
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	10-Feb-2020 14:54	SWL only. Clear sample. Slight yellow tint. Fine Very few brown particles at bottom of sample. Nil odour.	20.22
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	11-Feb-2020 12:54	Low Flow Pump. Clear sample. Clear. No particles in sample. Slight Sulphur odour. Cattle have damaged external cap.	53.763
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Feb-2020 10:24	Low Flow Pump. Very turbid sample. Yellow/brown Fine Brown silt at bottom of sample. Nil odour. Bore casing indicates 61m total depth, examination shows 20m.	15.382
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Feb-2020 08:13	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Nil damage.	38.544
R3	Regional 3 Landholder Monitoring bore located on Banyula property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	17-Feb-2020 15:42	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Slight Sulphur odour. Nil damage.	30.26
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	3-Feb-2020 15:07	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Nil damage.	32.241
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	3-Feb-2020 10:08	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage.	14.609
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	3-Feb-2020 07:56	Low Flow Pump. Clear sample. Clear No particles in sample. Nil odour. Nil damage	28.372
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Feb-2020 08:07	Low Flow Pump. Slightly turbid sample. No particles in sample. Nil odour.	37.287
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	11-Feb-2020 08:43	Low Flow Pump. Turbid sample. Black. Fine Black particles. Slight Sulphur odour.	59.881
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Feb-2020 09:16	Low Flow Pump. Slightly turbid sample. Light brown No particles in sample. Nil odour. Monument outer cap off upon arrival.	37.418
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	17-Feb-2020 14:32	Low Flow Pump. Clear sample. Clear colour. No particles in sample. Nil odour. Nil damage.	31.724
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	9-Feb-2020 12:30	Bailed. Clear sample. No particles in sample. Nil odour.	4.92
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	9-Feb-2020 07:53	Bailed. Cloudy sample. Grey colour No particles in sample. Nil odour. Nil damage Insufficient water to pump.	4.112
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	9-Feb-2020 08:19	Bailed. Clear sample. Clear. Course White (carbonate?) particles. Nil odour. Nil damage. Bailed 10 lt then sampled.	1.558
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 07:42	Dry. Dip tape stopped at 1.851 m.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	11-Feb-2020 13:29	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	30.884
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	11-Feb-2020 11:46	Low Flow Pump. Clear sample. Clear. No particles in sample. Nil odour. Nil damage.	23.981
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Feb-2020 08:20	Low Flow Pump. Clear sample. No particles in sample. Slight Organic odour. (Earthy odour).	27.39
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Feb-2020 09:23	Bailed. Turbid sample. Brown in colour. Course brown particles in sample. Strong Organic odour. (Earthy odour). Insufficient water to pump. Bailed 12L.	41.24
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Feb-2020 07:50	Low Flow Pump. Slightly turbid sample. Very light grey. No particles in sample. Nil odour. Nil damage.	28.921

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Feb-2020 08:31	Low Flow Pump. Turbid sample. Grey. No particles in sample. Nil odour. Nil damage.	36.962
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Feb-2020 12:45	Low Flow Pump. Clear sample. No particles in sample. Organic odour. (Earthy odour).	18.07
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Feb-2020 13:16	Low Flow Pump. Clear sample. No particles in sample. Strong Sulphur odour.	17.95
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Feb-2020 14:43	Low Flow Pump. Clear sample. No particles in sample. Slight Organic odour. (Earthy odour).	25.89
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Feb-2020 14:01	Low Flow Pump. Clear sample. No particles in sample. Organic odour. (Earthy odour).	28.77
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Feb-2020 09:57	Low Flow Pump. Clear sample. No particles in sample. Nil odour.	24.97