

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	8-Jul-2021 15:57	SWL only.	56.66
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	8-Jul-2021 16:03	SWL only.	53.57
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	8-Jul-2021 15:40	SWL only.	51.7
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Jul-2021 09:24	SWL only.	14.74
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-Jul-2021 12:13	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.14
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Jul-2021 11:16	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.33
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-Jul-2021 13:08	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8.43
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	8-Jul-2021 10:20	SWL only.	14.84
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Jul-2021 09:02	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.74
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Jul-2021 10:06	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.64
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Jul-2021 13:15	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.25
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Jul-2021 15:22	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.04
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-Jul-2021 09:12	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.	14.7
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	8-Jul-2021 15:49	SWL only.	41.67
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Jul-2021 15:17	Dry. Tape stopped at approx. 17m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Jul-2021 15:29	Bore bent. No sample collected. SWL only.	65.37
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	10-Jul-2021 11:49	SWL only.	46.53
MB3 RDH1097	Monitoring bore 3 - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	10-Jul-2021 11:21	SWL only.	37.54
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	15-Jul-2021 11:53	SWL only.	21.34
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	10-Jul-2021 09:28	SWL only.	59.86
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	15-Jul-2021 13:23	SWL only.	36.67
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	9-Jul-2021 07:49	SWL only.	63.32
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	15-Jul-2021 11:42	SWL only.	49.17
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Jul-2021 14:18	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.51
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Jul-2021 08:16	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	17.93
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Jul-2021 14:01	Bore blocked at approx. 1.2m. No sample collected. SWL only.	6.23
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	8-Jul-2021 09:37	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.79
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Jul-2021 08:46	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	20.98
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	8-Jul-2021 10:35	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.46
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Jul-2021 11:38	Bailer. Slightly turbid. Clear colour. Slight sulphur odour. Fine particles. White particles. Bailed 12L.	20.3
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2021 08:39	Blocked at approx. 28.09m. Ben Westerberg notified.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2021 08:49	SWL only.	15.67
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jul-2021 09:04	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.76
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-Jul-2021 15:37	SWL only.	56.1

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	9-Jul-2021 13:16	SWL only.	67.77
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-Jul-2021 12:45	SWL only.	174.89
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-Jul-2021 12:35	SWL only. SWL double checked and confirmed.	145.07
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-Jul-2021 14:18	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. Fine particles. Black particles. No pump in bore. Pumped at 50m.	30.33
R1	Regional 1 - Landholder monitoring bore located on Yarran property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	10-Jul-2021 08:57	SWL only. Bore blocked at approx. 42.65m. Ben Westerberg notified.	42.31
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	9-Jul-2021 15:10	SWL only.	18.61
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Jul-2021 11:01	SWL only.	53.15
R12	Regional 12 - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	14-Jul-2021 10:46	SWL only.	25.34
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2021 10:31	SWL only.	16.44
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2021 08:57	SWL only.	12.45
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	9-Jul-2021 08:00	SWL only.	20.52
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2021 00:02	Not Scheduled.	
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2021 09:07	SWL only.	15.93
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	10-Jul-2021 09:42	SWL only.	38.73
R3	Regional 3 Landholder Monitoring bore located on Banyula property - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	10-Jul-2021 10:33	SWL only.	30.47
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2021 11:13	SWL only.	32.8
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2021 12:32	SWL only.	14.74
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2021 12:12	SWL only.	28.25
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	10-Jul-2021 09:19	SWL only.	37.48
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	10-Jul-2021 09:22	SWL only.	59.78
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Jul-2021 09:55	SWL only.	39.55
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	9-Jul-2021 14:41	SWL only.	32.24
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	8-Jul-2021 14:05	Total depth approx. 8.40m. Insufficient water to pump and unsuccessful bailing bore. No sample collected. SWL only.	8.13
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	7-Jul-2021 13:58	Bailer. Slightly turbid. Light brown colour. Nil odour. Organic particles. Bailed 6L.	3.57
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	7-Jul-2021 14:54	Tap. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1.98
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Jul-2021 11:10	Dry. Tape stopped at approx. 1.8m. No sample collected.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	10-Jul-2021 11:35	SWL only.	31.02
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	10-Jul-2021 12:12	SWL only.	24.5
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	8-Jul-2021 07:55	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.94
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-Jul-2021 07:42	Bailer. Turbid. Dark brown colour. Strong organic odour. Fine particles. Brown particles. Bailed 6L. (Earthy odour).	40.64
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	6-Jul-2021 14:23	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. White particles. Bailed 6L.	29.06
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jul-2021 14:45	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.17
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	6-Jul-2021 10:05	Low Flow Pump. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy odour).	18.9
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jul-2021 10:44	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	18.77
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	6-Jul-2021 11:28	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.31
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jul-2021 12:09	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	29.62

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Jul-2021 10:54	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.16