

| Site   | Site Desc                                                                  | Site Type              | Site Category            | Date              | Comment_Field_Part 1                                                                                                                              | EC (Lab)<br>µS/cm | pH (Lab) | Sulfate<br>(SO4)<br>Turbidimetric mg/L |
|--------|----------------------------------------------------------------------------|------------------------|--------------------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------|----------------------------------------|
| 3067R  | Satellite bore to D2 lic AWL                                               | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 8-Apr-2021 14:05  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed. EC double checked and confirmed.              | 6380              | 7.66     | 1500                                   |
| 3069R  | Satellite bore to D2 - Basal Sand East lic AWL                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 8-Apr-2021 13:14  | Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.                                                                      | 2460              | 7.95     | 332                                    |
| 3072R  | Satellite bore to D1 lic AWL                                               | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 8-Apr-2021 14:45  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1300              | 8.02     | 42                                     |
| CD01   | Co-Disposal Series lic AWL                                                 | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 6-Apr-2021 13:29  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 7830              | 8.19     | 2380                                   |
| CD03   | Co-Disposal Series lic AWL                                                 | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 6-Apr-2021 14:10  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 5990              | 8.26     | 2610                                   |
| CD04   | Co-Disposal Series - Basal Sand East                                       | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 10-Apr-2021 07:30 | Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.                                                                      | 1440              | 8.08     | 26                                     |
| CD05   | Co-Disposal Series - Basalt East lic AWL                                   | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 10-Apr-2021 09:50 | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1390              | 8.1      | 34                                     |
| CD06   | Co-Disposal Series lic AWL                                                 | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 8-Apr-2021 10:49  | Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.                                                                             | 7070              | 7.72     | 3000                                   |
| KS2A   | Monitoring bore lic codisposal AWL                                         | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 11-Apr-2021 10:07 | Dry. Tape stopped at approx. 17m.                                                                                                                 |                   |          |                                        |
| KS2B   | Monitoring bore lic AWL                                                    | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 11-Apr-2021 10:18 | SWL only. Bore bent. No sample collected.                                                                                                         |                   |          |                                        |
| NB1    | Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 10-Apr-2021 08:46 | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1370              | 8.25     | 104                                    |
| NB2    | Monitoring bore - south of Kestrel rejects dam lic AWL                     | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 7-Apr-2021 07:36  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.                                                         | 3250              | 8.41     | 903                                    |
| NB5    | Monitoring bore AWL                                                        | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 11-Apr-2021 09:44 | SWL only. Bore blocked at approx. 1.2m. No sample collected.                                                                                      |                   |          |                                        |
| NF1A   | Near Field 1a - Basalt East codisposal AWL                                 | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 10-Apr-2021 12:37 | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1050              | 8.02     | 6                                      |
| NF1B   | Near Field 1b - Basal Sand East AWL                                        | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 10-Apr-2021 11:49 | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.                                                         | 1420              | 8.02     | 18                                     |
| NF2a   | Near Field 2a - Basalt East codisposal AWL                                 | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 10-Apr-2021 10:40 | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1100              | 8.17     | 52                                     |
| NF3b   | REF NF3b - Basal Sand East AWL                                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 10-Apr-2021 13:36 | Bailer. Not turbid. Clear colour. Slight sulphur odour. No particles. Bailed 12L.                                                                 | 1720              | 7.94     | 40                                     |
| NS3    | Monitoring bore - Basal Sand East lic AWL                                  | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 7-Apr-2021 08:27  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1050              | 8.58     | 25                                     |
| PB2    | Production bore 2 lic AWL                                                  | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 10-Apr-2021 14:17 | Low Flow Pump. Slightly turbid. Black colour. Sulphur odour. Fine particles. Black particles. Pump removed from bore. Bore pumped at approx. 45m. | 5440              | 7.8      | 2170                                   |
| SA1    | Shallow aquifer monitoring bore 1 lic AWL                                  | Bore - Shallow Aquifer | GROUNDWATER - CODISPOSAL | 11-Apr-2021 09:38 | Bailer. Slightly turbid. Grey colour. Nil odour. No particles. Bailed 6L. SWL double checked and confirmed.                                       | 8190              | 7.93     | 1820                                   |
| SA2    | Shallow aquifer monitoring bore 2 lic AWL                                  | Bore - Shallow Aquifer | GROUNDWATER - CODISPOSAL | 9-Apr-2021 10:45  | Bailer. Not turbid. Clear colour. Nil odour. No particles.                                                                                        | 15100             | 7.8      | 4070                                   |
| SA6    | Shallow aquifer monitoring bore 6 lic AWL                                  | Bore - Shallow Aquifer | GROUNDWATER - CODISPOSAL | 9-Apr-2021 10:54  | Bailer. Not turbid. Clear colour. Nil odour. No particles.                                                                                        | 11800             | 7.92     | 3010                                   |
| SA7    | Shallow aquifer monitoring bore 7 - lic AWL                                | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 9-Apr-2021 10:26  | Dry. Tape stopped at approx. 1.8m. No sample collected.                                                                                           |                   |          |                                        |
| SDB05A | compliance AWL                                                             | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 8-Apr-2021 12:12  | Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).                                                             | 1150              | 8.11     | 34                                     |
| SDB05B | compliance AWL                                                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 8-Apr-2021 11:52  | Bailer. Turbid. Dark brown colour. Organic odour. No particles. Brown particles. Bailed 5L.                                                       | 6860              | 12.4     | 4                                      |
| SDB06A | compliance AWL                                                             | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 7-Apr-2021 13:54  | Bailer. Not turbid. Clear colour. Slight organic odour. Fine particles. White particles. Bailed 6L. (Earthy odour).                               | 1280              | 8.49     | 22                                     |
| SDB06B | compliance AWL                                                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 7-Apr-2021 14:06  | Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).                                                             | 1030              | 8.73     | 33                                     |
| SDB07A | compliance AWL                                                             | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 7-Apr-2021 09:39  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 1010              | 8.67     | 25                                     |
| SDB07B | compliance AWL                                                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 7-Apr-2021 10:07  | Low Flow Pump. Not turbid. Clear colour. Strong organic odour. No particles.                                                                      | 1030              | 8.73     | 11                                     |
| SDB08A | compliance AWL                                                             | Bore - Basalt East     | GROUNDWATER - CODISPOSAL | 7-Apr-2021 11:52  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 2110              | 8.53     | 36                                     |
| SDB08B | compliance AWL                                                             | Bore - Basal Sand East | GROUNDWATER - CODISPOSAL | 7-Apr-2021 12:39  | Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.                                                                             | 2500              | 12       | 23                                     |
| T1     | Monitoring bore tertiary basalt lic AWL                                    | Bore - Tertiary Basalt | GROUNDWATER - CODISPOSAL | 6-Apr-2021 14:54  | Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.                                                                                 | 3430              | 8.3      | 1110                                   |