

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL)
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	16-Aug-2021 13:00	SWL only. SWL checked and confirmed. No access for pump or bailer. No sample collected.	133.07
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	13-Aug-2021 10:06	Low Flow Pump. Turbid. Light brown colour. Nil odour. No particles. Pumped at 59 m.	56.67
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	13-Aug-2021 10:59	Low Flow Pump. Slightly turbid. Yellow/brown colour. Nil odour. No particles.	53.58
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	13-Aug-2021 09:03	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	51.74
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	16-Aug-2021 14:52	No access for dipper tape. Headworks blocking access. No SWL.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 15:46	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.4
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	16-Aug-2021 14:44	SWL only. SWL double checked and confirmed. Unable to pump or bail. Ben Westerberg notified.	123.67
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	10-Aug-2021 14:40	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	14.75
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 09:38	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.27
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	13-Aug-2021 08:52	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.35
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 10:33	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8.65
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	14-Aug-2021 12:28	Low Flow Pump. Cloudy sample. Clear colour. Nil odour. Fine particles. Black particles.	14.9
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Aug-2021 11:09	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.71
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Aug-2021 12:14	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.63
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	14-Aug-2021 08:39	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.3
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	14-Aug-2021 10:29	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.13
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Aug-2021 09:00	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.	14.72
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Aug-2021 07:43	Dry. Tape stopped at 27.5 m.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	13-Aug-2021 07:51	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL rechecked and confirmed.	41.8
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 07:09	Dry. Tape stopped at 17.13 m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	13-Aug-2021 07:13	SWL only. Bore bent. Could not collect sample.	65.39
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	16-Aug-2021 15:04	No sample collected. SWL only. Ben Westerberg advised in Feb 2021 that doesn't need to be sampled.	162.94
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 08:25	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.04
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	11-Aug-2021 10:00	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	46.57
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	11-Aug-2021 08:43	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.61
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Aug-2021 11:02	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Black particles.	21.38
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Aug-2021 14:45	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Pump depth 64m.	59.99
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	11-Aug-2021 09:38	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. Fine particles. Brown particles. Pumped at 36m.	36.82
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 11:58	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	63.44
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Aug-2021 09:18	Low Flow Pump. Cloudy sample. Grey colour. Nil odour. Coarse particles. Brown particles. Pumped at 60m.	49.06

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL)
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	14-Aug-2021 09:40	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.56
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Aug-2021 08:14	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	17.94
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 08:13	Bore blocked at approx. 1.2m. No sample collected. SWL only.	6.24
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Aug-2021 15:08	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.81
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Aug-2021 14:20	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	21.03
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	14-Aug-2021 11:41	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.54
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	14-Aug-2021 11:16	Bailer. Not turbid. Clear colour. Sulphur odour. No particles. Bailed 12L.	20.34
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	17-Aug-2021 14:50	Blocked at approx. 27.89m. No Sample collected. Ben Westerberg notified.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Aug-2021 14:36	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. No particles.	15.69
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Aug-2021 07:18	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.79
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Aug-2021 07:31	SWL only. Top of casing badly damaged preventing deployment of sampling equipment.	55.99
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Aug-2021 09:27	Bailer. Cloudy sample. Clear colour. Strong sulphur odour. Fine particles. Black particles. Organic particles in sample. Bailed 6L. SWL double checked and confirmed.	65.1
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Aug-2021 13:35	Hydrasleeve. Slightly turbid. Clear colour. Slight sulphur odour. Fine particles. Black particles.	174.78
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Aug-2021 14:10	Hydrasleeve. Slightly turbid. Black colour. Sulphur odour. Fine particles. Black particles. SWL double checked and confirmed.	144.03
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Aug-2021 15:46	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. Fine particles. Black particles. No pump in bore. Pumped at 50m.	30.35
R1	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	12-Aug-2021 07:26	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	42.18
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Aug-2021 12:16	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.71
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 09:56	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	53.21
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	10-Aug-2021 07:16	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.36
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 07:16	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.11
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Aug-2021 11:45	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Microbubbles in sample.	16.45
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Aug-2021 13:25	Low Flow Pump. Turbid. Light brown colour. Nil odour. Organic particles. Brown particles.	12.47
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	10-Aug-2021 11:59	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.53
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	11-Aug-2021 07:39	Low Flow Pump. Cloudy sample. Grey colour. Slight sulphur odour. No particles.	54.79
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	10-Aug-2021 13:35	Low Flow Pump. Turbid. Yellow/brown colour. Nil odour. Fine particles. Yellow particles. TD 19m, SI 15-18m.	15.97
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	12-Aug-2021 09:19	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.74
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	11-Aug-2021 11:17	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	30.49
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	10-Aug-2021 09:59	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	32.87
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	12-Aug-2021 13:36	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	14.75
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Aug-2021 12:41	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	28.27

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL)
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	12-Aug-2021 07:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.49
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	12-Aug-2021 07:55	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Black particles.	59.77
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	11-Aug-2021 13:02	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. No particles. 251_QAQCD03 Taken- Yes.	40.04
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	11-Aug-2021 13:16	Low Flow Pump. Slightly turbid. Yellow/brown colour. Nil odour. Fine particles. Brown particles.	32.36
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	13-Aug-2021 08:10	Total depth approx. 8.40m. Insufficient water to pump or bail. No sample collected.	8.16
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	13-Aug-2021 12:13	Bailer. Not turbid. Clear colour. Nil odour. No particles. Disposable bailer tube. Bailed 6 L then sampled.	3.58
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	13-Aug-2021 11:53	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	2.08
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 12:32	Dry. Tape stopped at 1.8 m. No sample taken.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	11-Aug-2021 09:07	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. No particles.	31.06
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	11-Aug-2021 07:17	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. Fine particles. 251_QAQCD05 Taken- Yes.	24.57
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Aug-2021 12:59	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	28.02
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Aug-2021 13:46	Bailer. Turbid. Dark brown colour. Strong organic odour. Fine particles. Brown particles. Bailed 6L. (Earthy odour).	40.74
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Aug-2021 11:22	Bailer. Cloudy sample. Clear colour. Organic odour. Fine particles. White particles. Bailed 6L.	29.1
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Aug-2021 10:15	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.24
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Aug-2021 09:37	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.96
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Aug-2021 10:39	Low Flow Pump. Not turbid. Clear colour. Strong organic odour. No particles. (Earthy odour).	18.83
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Aug-2021 12:02	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.35
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Aug-2021 12:47	Low Flow Pump. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy odour).	29.68
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	13-Aug-2021 07:18	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.17