

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Oct-2021 15:59	SWL only.	56.44
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Oct-2021 15:35	SWL only.	53.27
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Oct-2021 15:19	SWL only.	51.49
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	13-Oct-2021 10:33	SWL only.	14.82
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Oct-2021 15:49	Low Flow Pump. Not turbid. Clear colour. Nil odour.	6.1
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Oct-2021 15:13	Low Flow Pump. Not turbid. Clear colour. Nil odour.	16.25
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Oct-2021 14:27	Low Flow Pump. Not turbid. Clear colour. Nil odour.	8.36
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	9-Oct-2021 11:44	SWL only.	14.87
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Oct-2021 08:48	Low Flow Pump. Not turbid. Clear colour. Nil odour.	19.98
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Oct-2021 09:35	Low Flow Pump. Not turbid. Clear colour. Nil odour.	30.93
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Oct-2021 10:54	Low Flow Pump. Not turbid. Clear colour. Nil odour.	32.33
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Oct-2021 15:06	Low Flow Pump. Not turbid. Clear colour. Nil odour.	24.35
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-Oct-2021 08:10	Low Flow Pump. Not turbid. Clear colour. Slight	14.88
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	12-Oct-2021 15:13	SWL double checked and confirmed.	42.24
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Oct-2021 14:52	Dry. Tape stopped at approx. 17.01m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Oct-2021 14:55	Bore bent. No sample collected. SWL only.	65.19
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	13-Oct-2021 12:27	SWL only.	46.65
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Oct-2021 12:57	SWL only.	37.58
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Oct-2021 13:08	SWL only.	21.32
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Oct-2021 13:45	SWL only.	59.97
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Oct-2021 12:48	SWL only.	36.87
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 15:25	SWL only.	63.41
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Oct-2021 13:15	SWL only.	53.34
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-Oct-2021 14:23	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.78
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-Oct-2021 11:09	Low Flow Pump. Not turbid. Clear colour. Nil odour.	18.02
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Oct-2021 14:36	Bore blocked at approx. 1.2m. No sample collected.	6.62
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Oct-2021 12:17	Low Flow Pump. Not turbid. Clear colour. Nil odour.	16.87
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Oct-2021 11:48	Low Flow Pump. Not turbid. Clear colour. Nil odour.	21.17
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Oct-2021 13:07	Low Flow Pump. Not turbid. Clear colour. Nil odour.	23.59
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Oct-2021 13:50	Bailer. Not turbid. Clear colour. Sulphur odour. No	20.36
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Oct-2021 11:35	SWL only. Dry / Blocked. Tape stopped at 28.02m.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Oct-2021 11:05	SWL only.	15.77
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Oct-2021 10:26	Low Flow Pump. Not turbid. Clear colour. Nil odour.	32.72
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Oct-2021 15:06	SWL only.	55.7
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	5-Oct-2021 14:18	SWL only.	64.98
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Oct-2021 09:40	SWL only.	174.88
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Oct-2021 09:31	SWL only. SWL double checked and confirmed.	142.56
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Oct-2021 10:50	Pump in bore. Not pumping at time of collection. No	30.68
R1	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Oct-2021 08:21	SWL only.	42.68

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Oct-2021 14:24	SWL only.	18.65
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 14:50	SWL only.	53.22
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Oct-2021 11:33	SWL only.	25.37
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Oct-2021 12:16	SWL only.	16.48
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Oct-2021 10:44	SWL only.	12.48
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Oct-2021 15:33	SWL only.	20.59
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Oct-2021 00:02	Not Scheduled.	
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Oct-2021 10:55	SWL only.	15.99
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Oct-2021 08:53	SWL only.	38.72
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Oct-2021 09:33	SWL only.	30.46
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 14:38	SWL only.	32.87
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Oct-2021 11:10	SWL only.	14.82
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 10:53	SWL only.	28.22
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Oct-2021 13:33	SWL only.	37.42
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Oct-2021 13:36	SWL only.	59.72
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 14:07	SWL only. SWL double checked and confirmed.	36.92
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Oct-2021 14:19	SWL only.	32.29
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	12-Oct-2021 14:39	Total depth approx. 8.53m. Insufficient water to	8.51
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	6-Oct-2021 13:49	Bailer. Not turbid. Clear colour. Nil odour. Organic	3.19
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	6-Oct-2021 12:35	Bailer. Not turbid. Clear colour. Nil odour. No	1.87
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Oct-2021 14:18	Dry. Tape stopped at approx. 1.8m. No sample	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Oct-2021 12:14	SWL only.	30.92
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Oct-2021 11:53	SWL only.	24.49
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Oct-2021 13:08	Low Flow Pump. Not turbid. Clear colour. Nil odour.	28.01
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Oct-2021 12:57	Bailer. Turbid. Dark brown colour. Strong organic	40.69
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Oct-2021 11:49	Bailer. Not turbid. Clear colour. Nil odour. No	29.09
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Oct-2021 12:01	Low Flow Pump. Not turbid. Clear colour. Nil odour.	37.23
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	7-Oct-2021 12:13	Low Flow Pump. Not turbid. Clear colour. Nil odour.	19.01
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Oct-2021 12:47	Low Flow Pump. Not turbid. Clear colour. Slight	18.86
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	7-Oct-2021 13:46	Low Flow Pump. Not turbid. Clear colour. Nil odour.	27.5
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Oct-2021 14:22	Low Flow Pump. Not turbid. Clear colour. Slight	29.65
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Oct-2021 10:13	Low Flow Pump. Not turbid. Clear colour. Nil odour.	26.47