

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 09:35	SWL only. SWL double checked and confirmed.	131.16
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	6-Nov-2021 08:36	SWL only.	56.51
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	6-Nov-2021 08:30	SWL only.	53.33
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	6-Nov-2021 08:51	SWL only.	51.55
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 08:10	No access for dipper tape. Headworks blocking access. No SWL.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 08:15	SWL only. SWL double checked and confirmed.	121.85
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	6-Nov-2021 09:44	SWL only.	14.83
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 10:58	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.34
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	3-Nov-2021 10:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.37
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 11:44	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8.6
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	4-Nov-2021 13:57	SWL only.	14.99
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	1-Nov-2021 12:14	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.11
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-Nov-2021 08:51	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.12
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 10:31	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.41
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	1-Nov-2021 15:06	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.46
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 09:09	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.	15.01
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 08:57	Dry. Tape stopped at approx. 27.54m.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	6-Nov-2021 08:50	SWL only.	42.41
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2021 09:20	Dry. Tape stopped at approx. 17.02m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Nov-2021 09:24	Bore bent. No sample collected. SWL only.	65.28
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	6-Nov-2021 11:50	SWL only.	37.62
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	6-Nov-2021 12:43	SWL only.	21.36
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	5-Nov-2021 12:01	SWL only.	60.02
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 12:56	SWL only.	53.43
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	1-Nov-2021 14:22	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.91
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	2-Nov-2021 10:07	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	18.12
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:36	Bore blocked at approx. 1.2m. No sample collected. SWL only.	6.87
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 13:08	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.87
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 12:29	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	21.21
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 11:28	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.66

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:02	Bailer. Cloudy sample. Clear colour. Nil odour. Fine particles. White particles. Bailed 12L.	20.38
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 10:26	Dry/blocked. Tape stopped at approx. 28.04m.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2021 10:13	SWL only.	15.79
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 09:20	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.79
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-Nov-2021 09:12	SWL only.	55.78
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Nov-2021 00:02	Not Scheduled.	
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	1-Nov-2021 15:53	Pump in bore. Not pumping at time of collection. No sample collected.	30.75
R1	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	5-Nov-2021 11:44	SWL only.	42.81
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	5-Nov-2021 13:11	SWL only.	18.69
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 12:21	SWL only.	53.27
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	6-Nov-2021 10:48	SWL only.	25.38
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 10:38	SWL only.	37.92
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 13:25	SWL only.	16.49
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2021 09:53	SWL only.	12.48
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	6-Nov-2021 13:09	SWL only.	20.61
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 11:27	SWL only.	54.9
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-Nov-2021 10:07	SWL only.	16.01
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	5-Nov-2021 12:18	SWL only.	38.69
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	5-Nov-2021 12:54	SWL only.	30.5
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	5-Nov-2021 13:21	SWL only.	32.92
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	5-Nov-2021 14:10	SWL only.	14.82
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	5-Nov-2021 14:29	SWL only.	28.2
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	5-Nov-2021 11:50	SWL only.	37.46
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	5-Nov-2021 11:52	SWL only.	59.73
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-Nov-2021 12:38	SWL only. 251_QAQCD03 Taken- No.	36.96
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	5-Nov-2021 12:37	SWL only.	32.3
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:39	Dry. Tape stopped at approx. 8.51m. No sample collected.	
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	3-Nov-2021 14:51	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L. SWL and EC double checked and confirmed.	3.61
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	3-Nov-2021 13:40	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	2.08
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 15:12	Dry. Tape stopped at approx. 1.8m. No Sample collected.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	6-Nov-2021 11:38	SWL only.	30.93
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	6-Nov-2021 11:02	SWL only. 251_QAQCD05 Taken- No.	24.53
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 14:11	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	28.04
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 14:50	Bailer. Turbid. Grey colour. Strong organic odour. Fine particles. White particles. Insufficient water to pump. Bailed 6L. (Earthy odour).	41.05

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	2-Nov-2021 14:18	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	29.08
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 14:37	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.2
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	2-Nov-2021 11:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.1
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 12:06	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.	18.96
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 15:33	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.42
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 16:23	Low Flow Pump. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy odour). EC double checked and confirmed.	29.8
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-Nov-2021 09:39	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.64