

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Electrical Conductivity (Lab) µS/cm	pH (Lab) pH	Sulfate(SO4 2-) _Turbidimetric mg/L
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 10:58	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8530	7.05	1950
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	3-Nov-2021 10:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2440	7.52	338
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 11:44	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1250	7.61	38
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	1-Nov-2021 12:14	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8340	7.57	2300
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-Nov-2021 08:51	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	5870	7.76	2410
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 10:31	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1400	8.16	27
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	1-Nov-2021 15:06	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1350	7.82	33
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 09:09	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.			
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 09:38		7130	7.25	2950
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Nov-2021 09:20	Dry. Tape stopped at approx. 17.02m.			
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Nov-2021 09:24	Bore bent. No sample collected. SWL only.			
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	1-Nov-2021 14:22	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1320	8.01	95
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	2-Nov-2021 10:07	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	4050	7.55	824
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:36	Bore blocked at approx. 1.2m. No sample collected. SWL only.			
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 13:08	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1040	8.02	6
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 12:29	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	1400	7.99	16
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 11:28	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1080	8.23	47
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:02	Bailer. Cloudy sample. Clear colour. Nil odour. Fine particles. White particles. Bailed 12L.	1680	7.87	36
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 09:20	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1060	7.78	18
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	1-Nov-2021 15:53	Pump in bore. Not pumping at time of collection. No sample collected.			
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	5-Nov-2021 10:39	Dry. Tape stopped at approx. 8.51m. No sample collected.			
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	3-Nov-2021 14:51	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L. SWL and EC double checked and confirmed.	12200	7.45	3490
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	3-Nov-2021 13:40	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	10900	7.61	2630
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	3-Nov-2021 15:12	Dry. Tape stopped at approx. 1.8m. No Sample collected.			
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 14:11	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1140	8.13	29
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 14:50	Bailer. Turbid. Grey colour. Strong organic odour. Fine particles. White particles. Insufficient water to pump. Bailed 6L. (Earthy odour).	6800	12.4	5
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	2-Nov-2021 14:18	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1360	8.03	20
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 14:37	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1040	8.42	27
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	2-Nov-2021 11:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1060	8.04	27
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	2-Nov-2021 12:06	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.	1050	8.2	12
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 15:33	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.			
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-Nov-2021 15:43		2200	8.04	33
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-Nov-2021 16:23	Low Flow Pump. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy odour). EC double checked and confirmed.	3180	12	19
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-Nov-2021 09:39	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	3430	7.94	1140