Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water
						Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-May-2022 11:44	SWL only. SWL double checked and confirmed.	129.15
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	3-May-2022 13:00	SWL only.	56.54
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND		SWL only.	53.18
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND GROUNDWATER - PERMIAN	3-May-2022 12:19		51.45
301N 3028D	301N 300 series GOAF Monitoring Bore AWL 3028D AWL	Bore - Permian GC seam Bore - Permian sandstone	GROUNDWATER - PERMIAN GROUNDWATER - PERMIAN	8-May-2022 16:05 1-May-2022 00:02	No access for dipper tape. Headworks blocking access. No SWL. Not Scheduled.	
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-May-2022 15:55	SWL only. SWL double checked and confirmed.	119.91
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	3-May-2022 13:34	SWL only.	15.04
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-May-2022 09:22	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	6.7
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	8-May-2022 10:11	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.45
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	8-May-2022 08:27	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8.34
62641 CD01	Monitoring bore located North of Gordon Downs Homestead licence AWL Co-Disposal Series lic AWL	Bore - Tertiary Basalt Bore - Tertiary Basalt	GROUNDWATER - BASALT GROUNDWATER - CODISPOSAL	5-May-2022 10:45 7-May-2022 09:37	SWL only. Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.18 20.87
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-May-2022 10:23	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.57
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-May-2022 12:50	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.7
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	7-May-2022 14:17	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.03
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	4-May-2022 13:54	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles.	15.47
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN		Dry. Tape stopped at approx. 27.58m.	
KS1F KS2A	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	3-May-2022 12:22	, ,	43.46
KS2B	Monitoring bore lic codisposal AWL Monitoring bore lic AWL	Bore - Tertiary Basalt Bore - Basal Sand East	GROUNDWATER - CODISPOSAL GROUNDWATER - CODISPOSAL	3-May-2022 11:51 3-May-2022 11:55	Dry. Tape stopped at approx. 17.20m. Bore bent. No sample collected. SWL only.	65.34
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	03.34
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	8-May-2022 12:44	SWL only.	46.78
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	8-May-2022 13:07	SWL only.	37.74
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	8-May-2022 15:24	SWL only.	21.49
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	6-May-2022 09:34	SWL only.	60.21
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	8-May-2022 12:55	,	37.12
MB7 RDH1304 MB8 RDH1009	Monitoring bore 7 permian AWL Monitoring bore 8 AWL	Bore - Permian Corvus sandstone Bore - Permian GC seam	GROUNDWATER - PERMIAN GROUNDWATER - PERMIAN	8-May-2022 12:03 1-May-2022 00:02	Not Scheduled.	63.67
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL		Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.45
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	· ·	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251 QAQCD01 Taken-Yes.	18.49
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-May-2022 15:16	Bore blocked at approx.1.2m. No sample collected.	7.59
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-May-2022 08:01	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	17.02
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	5-May-2022 08:28	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	21.35
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	5-May-2022 09:29	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. Fine particles. Brown particles.	23.86
NF3b	REF NF3b - Basal Sand East AWL Near Field 5 AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL GROUNDWATER - PERMIAN	5-May-2022 09:07 1-May-2022 00:02	Bailer. Cloudy sample. Clear colour. Slight sulphur odour. No particles. Water profile too small to pump a sample. Bailed 12L then took a sample. Not Scheduled.	20.49
NF5 NF6	Near Field 5 AWL Near Field 6 - Basalt East AWL	Bore - Permian sandstone Bore - Basalt East	GROUNDWATER - PERIMIAN GROUNDWATER - BASALT	3-May-2022 14:11	SWL only.	16.01
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	3-May-2022 14:11	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.86
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-May-2022 00:02	Not Scheduled.	
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt Bore - Basal Sand West	GROUNDWATER - CODISPOSAL GROUNDWATER - BASAL SAND	7-May-2022 15:09	Pump in bore. Not pumping at time of collection. No sample collected. SWL only.	31.29
R10	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Basal Sand West Bore - Tertiary Basalt	GROUNDWATER - BASAL SAND	6-May-2022 09:09 6-May-2022 11:59	SWL only.	43.62 18.78
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-May-2022 11:42		53.58
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	3-May-2022 15:01		25.42
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	3-May-2022 14:49	SWL double checked and confirmed.	38.75
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	3-May-2022 14:40	SWL only.	16.48
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	3-May-2022 13:42		12.58
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	8-May-2022 12:07		20.68
R17 R18A	Regional 17 AWL REF R18a - Landholder Basalt East AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	8-May-2022 12:24	,	55.04
R18A R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt East Bore - Basalt West	GROUNDWATER - BASALT GROUNDWATER - BASALT	3-May-2022 13:52 6-May-2022 09:50		16.21 38.77
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	6-May-2022 10:14		30.64
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-May-2022 10:43	, ,	33.07
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	6-May-2022 06:55	SWL only.	14.51
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	6-May-2022 07:17		28.11
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	6-May-2022 12:23		37.41
R7B R8	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER BERMAN	6-May-2022 12:28		59.71
R9	Regional 8 - Landholder monitoring bore located on Kelam property AWL Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone Bore - Permian sandstone	GROUNDWATER - PERMIAN GROUNDWATER - PERMIAN	6-May-2022 12:14 6-May-2022 12:06	SWL only. 251_QAQCD03 Taken- No. SWL only.	37.11 32.32
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - PERIMIAN GROUNDWATER - CODISPOSAL	7-May-2022 15:18	Dry. Tape stopped at approx. 8.50m. No sample collected.	32.32
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL		Dry. Tape stopped at approx. 4.70m. No sample collected.	
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL		Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	2.2
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	-	Dry. Tape stopped at approx. 1.80m. No sample collected.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	8-May-2022 12:36		30.99
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND		SWL only. 251_QAQCD05 Taken- No.	24.7
SDB05A SDB05B	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	· ·	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	28.19 40.69
SDB05B	compliance AWL compliance AWL	Bore - Basal Sand East Bore - Basalt East	GROUNDWATER - CODISPOSAL GROUNDWATER - CODISPOSAL		Bailer. Water profile insufficient to pump a sample. Bailed 6L then collected a sample. Bailer. Not turbid. Clear colour. Nil odour. No particles. Water profile insufficient to pump a sample. Bailed 6L then took a sample.	29.05
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL		Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.28
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-May-2022 08:32	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.32
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-May-2022 09:08	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.	19.2
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	4-May-2022 10:46	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	28.09
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	4-May-2022 11:18	Low Flow Pump. Not turbid. Clear colour. Strong organic odour. No particles.	30.07
	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	7-May-2022 11:21	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.05