

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Jun-2022 09:15	SWL only.	56.48
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Jun-2022 09:24	SWL only.	53.21
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Jun-2022 08:51	SWL only.	51.5
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Jun-2022 11:12	SWL only.	23.84
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	12-Jun-2022 09:48	SWL only.	15.14
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Jun-2022 12:28	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL and EC double checked and confirmed.	5.11
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Jun-2022 11:40	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.44
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Jun-2022 11:01	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	7.56
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	11-Jun-2022 10:52	SWL only.	14.97
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Jun-2022 08:58	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.46
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Jun-2022 09:53	SWL only. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	30.82
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Jun-2022 12:49	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.58
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Jun-2022 14:32	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	24.28
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Jun-2022 13:42	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. Fine particles.	14.68
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Jun-2022 08:58	Dry. Tape stopped at approx. 27.61m.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	12-Jun-2022 08:56	SWL only.	43.56
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Jun-2022 08:30	Dry. Tape stopped at approx. 17.23m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Jun-2022 08:33	Bore bent. No sample collected. SWL only.	65.42
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	17-Jun-2022 13:16	SWL only.	162.52
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	16-Jun-2022 06:53	SWL only.	37.49
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	12-Jun-2022 12:54	SWL only.	37.76
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Jun-2022 13:50	SWL only.	21.45
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Jun-2022 10:34	SWL only.	60.27
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	17-Jun-2022 12:53	SWL only.	45.02
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Jun-2022 13:43	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.69
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	6-Jun-2022 11:10	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	17.72
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jun-2022 15:09	Bore blocked at approx. 1.2m. No sample collected. SWL only.	7.17
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Jun-2022 10:04	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	17.07
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Jun-2022 08:46	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	21.23
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Jun-2022 11:19	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.71
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Jun-2022 12:03	Bailer. Not turbid. Clear colour. Slight sulphur odour. No particles. Bailed 12L.	20.52
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Jun-2022 11:05	Dry. Bore blocked at approx. 28.17m.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	12-Jun-2022 10:58	SWL only.	16.08
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jun-2022 11:46	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.85
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Jun-2022 08:41	SWL only.	55.83
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jun-2022 00:02	Not Scheduled.	
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jun-2022 14:59	Pump in bore. Not pumping at time of collection. No sample collected. SWL only. SWL double checked and confirmed.	30.51
R1	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Jun-2022 09:08	SWL only.	43.05
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	12-Jun-2022 13:04	SWL only.	18.91
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Jun-2022 13:25	SWL only.	53.63
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	12-Jun-2022 11:41	SWL only.	25.38
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Jun-2022 11:26	SWL only.	38.97
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	16-Jun-2022 14:40	SWL only.	16.44
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	12-Jun-2022 10:01	SWL only.	12.58
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	8-Jun-2022 08:20	SWL only.	20.63
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	12-Jun-2022 12:27	SWL only.	55.02
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	12-Jun-2022 10:22	SWL only.	16.28
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Jun-2022 10:49	SWL only.	38.8
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Jun-2022 12:18	SWL only.	30.61
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jun-2022 12:57	SWL only.	33.1
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Jun-2022 14:49	SWL only.	14.36
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jun-2022 15:13	SWL only.	28.1
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	12-Jun-2022 13:44	SWL only.	37.48
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	12-Jun-2022 13:42	SWL only.	59.72
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	17-Jun-2022 12:32	SWL only. 251_QAQCD03 Taken- No.	37.2
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	8-Jun-2022 15:08	SWL only.	32.3
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	11-Jun-2022 15:13	Dry. Tape stopped at approx. 8.52m. No sample collected.	
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	10-Jun-2022 09:38	Bailer. Not turbid. Clear colour. Slight sulphur odour. Organic particles. SWL and EC double checked and confirmed. Bailed 6L.	2.31
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	10-Jun-2022 09:16	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1.65
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Jun-2022 09:53	Dry. Tape stopped at approx. 1.80m. No sample collected.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	12-Jun-2022 12:39	SWL only.	30.99
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	12-Jun-2022 12:13	SWL only. 251_QAQCD05 Taken- No.	24.77
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Jun-2022 14:59	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.92
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Jun-2022 14:51	Bailer. Turbid. Grey colour. Organic odour. Fine particles. White particles. (Earthy odour).	40.58
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	6-Jun-2022 12:28	Bailer. Not turbid. Clear colour. Nil odour. No particles. Water profile insufficient to pump a sample. Bailed 6L then took a sample.	29.1

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	6-Jun-2022 12:36	Low Flow Pump. Cloudy sample. Clear colour. Nil odour. No particles.	37.28
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	7-Jun-2022 08:42	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.19
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Jun-2022 09:23	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.	19.05
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	7-Jun-2022 07:24	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.69
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	7-Jun-2022 07:58	Low Flow Pump. Not turbid. Clear colour. Strong organic odour. No particles.	29.97
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Jun-2022 10:30	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	26.33