

Site	Site Desc	Site Type	Site Category	Date	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	202 bore goaf AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
300-MB04	300 series bore compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Jul-2022 13:41	SWL only.	56.44
300-MB11	300 Series Monitoring Borehole compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Jul-2022 13:51	SWL only.	53.18
300-MB36	Basal Sand - Basal Sand East compliance AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Jul-2022 12:36	SWL only.	51.45
301N	301N 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
3028D	3028D AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
303	303 300 series GOAF Monitoring Bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Jul-2022 12:55	SWL only.	119.87
3045D	Monitoring bore - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - BASAL SAND	14-Jul-2022 14:33	SWL only.	15.16
3067R	Satellite bore to D2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jul-2022 12:18	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	4.48
3069R	Satellite bore to D2 - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Jul-2022 11:30	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.43
3072R	Satellite bore to D1 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jul-2022 10:53	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	7.39
62641	Monitoring bore located North of Gordon Downs Homestead licence AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	9-Jul-2022 12:07	SWL only.	14.93
CD01	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	14-Jul-2022 10:17	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.4
CD03	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jul-2022 10:33	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.59
CD04	Co-Disposal Series - Basal Sand East	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Jul-2022 11:20	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.57
CD05	Co-Disposal Series - Basalt East lic AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Jul-2022 12:53	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.42
CD06	Co-Disposal Series lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	9-Jul-2022 15:34	Low Flow Pump. Not turbid. Clear colour. Sulphur odour.	14.87
KS1D	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Jul-2022 12:28	Dry. Tape stopped at 27.61m.	
KS1F	Test production bore AWL	Bore - Tertiary Basal Sand	GROUNDWATER - BASAL SAND	14-Jul-2022 12:26	SWL only.	43.59
KS2A	Monitoring bore lic codisposal AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	14-Jul-2022 11:20	Dry. Tape stopped at 17.21m.	
KS2B	Monitoring bore lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	14-Jul-2022 11:27	SWL only.	65.43
KS4A	Monitoring bore AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
MB1 RDH1357	Monitoring bore 1 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
MB2 RDH1338	Monitoring Bore 2 AWL	Bore - Permian Corvus seam	GROUNDWATER - PERMIAN	13-Jul-2022 15:24	SWL only.	46.89
MB3 RDH1097	Monitoring bore 3 REF - Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Jul-2022 15:57	SWL only.	37.74
MB4 RDH1336	Monitoring bore 4 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Jul-2022 16:25	SWL only.	21.4
MB5 DDH435	Monitoring bore 5 Landholder AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Jul-2022 12:06	SWL only.	60.25
MB6 RDH1015	Monitoring bore 6 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Jul-2022 16:06	SWL only.	37.15
MB7 RDH1304	Monitoring bore 7 permian AWL	Bore - Permian Corvus sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 14:42	SWL only.	63.7
MB8 RDH1009	Monitoring bore 8 AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	13-Jul-2022 15:09	SWL only.	44.92
NB1	Monitoring bore - east of Kestrel rejects dam - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	12-Jul-2022 11:55	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.87
NB2	Monitoring bore - south of Kestrel rejects dam lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	10-Jul-2022 08:59	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes. EC double checked and confirmed.	17.68
NB5	Monitoring bore AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Jul-2022 16:19	Bore blocked at approx. 1.2m. No sample collected.	7.27
NF1A	Near Field 1a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Jul-2022 11:12	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	17.03
NF1B	Near Field 1b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Jul-2022 10:23	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	21.13
NF2a	Near Field 2a - Basalt East codisposal AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Jul-2022 08:51	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.65
NF3b	REF NF3b - Basal Sand East AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	12-Jul-2022 13:47	Bailer. Not turbid. Clear colour. Sulphur odour. No particles. Bailed 12L.	20.52
NF5	Near Field 5 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2022 15:15	Dry. Tape stopped at 28.13m.	
NF6	Near Field 6 - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2022 14:24	SWL only.	16.12
NS3	Monitoring bore - Basal Sand East lic AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Jul-2022 08:17	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	32.87
P1	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Jul-2022 11:42	SWL only.	55.95
P2	Monitoring bore lic, north of 200's AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	12-Jul-2022 16:09	SWL only. SWL double checked and confirmed.	60.45
P3	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Jul-2022 09:04	SWL only. Grass around bore needs slashing to improve visibility and safety.	173.98
P4	Monitoring bore lic AWL	Bore - Permian GC seam	GROUNDWATER - PERMIAN	14-Jul-2022 08:57	SWL only. Grass around bore to be slashed.	140.31
PB2	Production bore 2 lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	12-Jul-2022 11:04	Pump in bore. Not pumping. No sample collected. SWL only.	30.73
R1	Regional 1 - Landholder monitoring bore located on Yarran property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	15-Jul-2022 12:41	SWL only.	43.22
R10	Regional 10 - Landholder monitoring bore located on All's Well property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Jul-2022 10:35	SWL only.	18.93
R11	Regional 11 Landholder bore on Nesnah AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 09:39	SWL only.	53.68
R12	Regional 12 REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	14-Jul-2022 15:53	SWL only.	25.38
R13	Regional 13 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
R14	Regional 14 Top Langley AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	14-Jul-2022 15:50	SWL only.	16.47
R15A	Regional 15a - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2022 14:41	SWL only.	12.6
R16	Regional 16 AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Jul-2022 14:35	SWL only.	20.72
R17	Regional 17 AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	1-Jul-2022 00:02	Not Scheduled.	
R18A	REF R18a - Landholder Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	14-Jul-2022 14:52	SWL only.	16.28
R2	REF Regional 2 - Landholder Basalt West AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Jul-2022 11:50	SWL only.	38.77
R3	Regional 3 Landholder Monitoring bore located on Banyula property REF - Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	15-Jul-2022 13:32	SWL only.	30.62
R4	Regional 4 - Landholder Monitoring bore located on Werrina Downs property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 10:03	SWL only.	33.1
R5	Regional 5 - Landholder Monitoring bore located on Langley Downs property - Basalt East AWL	Bore - Basalt East	GROUNDWATER - BASALT	13-Jul-2022 07:10	SWL only.	14.31
R6	Regional 6 - Landholder Monitoring bore located on Yapunya property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 06:47	SWL only.	28.09
R7A	Regional 7a - Landholder Monitoring bore located on Kevricia property AWL	Bore - Tertiary Basalt	GROUNDWATER - BASALT	13-Jul-2022 12:28	SWL only.	37.4
R7B	REF Regional 7b - Landholder Basal Sand West AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	13-Jul-2022 12:33	SWL only.	59.72
R8	Regional 8 - Landholder monitoring bore located on Kelam property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 11:23	SWL only. 251_QAQCD03 Taken- No.	37.15
R9	Regional 9 - Landholder monitoring bore located on It'll Do property AWL	Bore - Permian sandstone	GROUNDWATER - PERMIAN	13-Jul-2022 10:52	SWL only.	32.36
SA1	Shallow aquifer monitoring bore 1 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	12-Jul-2022 16:21	Dry. Tape stopped at approx. 8.50m. No sample collected.	
SA2	Shallow aquifer monitoring bore 2 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	11-Jul-2022 10:45	Bailer. Not turbid. Clear colour. Slight sulphur odour. Organic particles. Bailed 6L. EC double checked and confirmed.	2.07
SA6	Shallow aquifer monitoring bore 6 lic AWL	Bore - Shallow Aquifer	GROUNDWATER - CODISPOSAL	11-Jul-2022 10:20	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1.48
SA7	Shallow aquifer monitoring bore 7 - lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	11-Jul-2022 10:48	Dry. Tape stopped at approx. 1.80m. No sample collected.	
SDB01A	Basalt West compliance AWL	Bore - Basalt West	GROUNDWATER - BASALT	13-Jul-2022 15:32	SWL only.	30.95
SDB03B	Basal Sand West - Compliance AWL	Bore - Basal Sand West	GROUNDWATER - BASAL SAND	14-Jul-2022 15:33	SWL only. 251_QAQCD05 Taken- No. SWL checked twice and confirmed.	24.76
SDB05A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	9-Jul-2022 13:02	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.8
SDB05B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	9-Jul-2022 12:43	Bailer. Turbid. Grey colour. Organic odour. Fine particles. White particles. (Earthy odour). Bailed 6L.	40.46
SDB06A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	11-Jul-2022 15:33	Bailer. Not turbid. Clear colour. Nil odour. No particles. Water profile insufficient to pump. Bailed 6L.	29.08
SDB06B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	11-Jul-2022 15:43	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.27
SDB07A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Jul-2022 10:01	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.02
SDB07B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Jul-2022 10:38	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	18.88
SDB08A	compliance AWL	Bore - Basalt East	GROUNDWATER - CODISPOSAL	10-Jul-2022 11:34	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.72
SDB08B	compliance AWL	Bore - Basal Sand East	GROUNDWATER - CODISPOSAL	10-Jul-2022 12:15	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29.5
T1	Monitoring bore tertiary basalt lic AWL	Bore - Tertiary Basalt	GROUNDWATER - CODISPOSAL	14-Jul-2022 09:25	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	26.55