

Site	Date	Other Tags	Comment_Field_Part 1	Electrical Conductivity (Lab) µS/cm	pH (Lab) pH	Sulfate(SO4 2-)_Turbidimetric mg/L
3067R	14-Dec-2022 13:40:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked.	2380	7.9	409
3069R	14-Dec-2022 12:48:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1530	7.95	375
3072R	14-Dec-2022 11:33:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1260	8	44
CD01	20-Dec-2022 11:59:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	8050	7.9	2790
CD03	20-Dec-2022 12:53:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	3330	7.74	2660
CD04	20-Dec-2022 15:51:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1470	7.72	36
CD05	21-Dec-2022 10:29:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1370	7.8	35
CD06	20-Dec-2022 10:09:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL & EC doubled checked and confirmed.	3650	7.76	2750
KS2A	22-Dec-2022 13:55:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 17.41m.			
KS2B	22-Dec-2022 13:58:00	GROUNDWATER - CODISPOSAL	Bore bent, no sample collected. SWL only.			
NB1	21-Dec-2022 08:59:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1240	8.18	46
NB2	14-Dec-2022 15:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251 QAQCD01 Taken- Yes. SWL double checked and confirmed.	6390	7.77	1030
NB5	22-Dec-2022 13:24:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Bore blocked at approx. 1.2m. No sample collected. SWL double checked and confirmed.			
NF1A	21-Dec-2022 13:47:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1070	8.03	8
NF1B	21-Dec-2022 12:50:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251 QAQCD02 Taken- Yes.	1380	7.94	18
NF2a	21-Dec-2022 12:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1060	8.2	46
NF3b	21-Dec-2022 11:39:00	GROUNDWATER - CODISPOSAL	Bailer. Cloudy sample. Clear colour. Slight sulphur odour. No particles. Bailed 12L.	1620	7.77	35
NS3	19-Dec-2022 10:05:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1020	8.14	40
PB2	20-Dec-2022 14:51:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Not pumping. No sample collected. SWL only.			
SA1	22-Dec-2022 13:27:00	GROUNDWATER - CODISPOSAL	SWL only. Insufficient water to pump or bail. No sample collected. SWL only. SWL double checked and confirmed.			
SA2	14-Dec-2022 11:16:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Slight sulphur odour. Organic particles. Bailed 6L.	10200	7.79	3260
SA6	14-Dec-2022 10:55:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	11200	7.42	2990
SA7	21-Dec-2022 16:46:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.80m. No sample collected.			
SDB05A	21-Dec-2022 15:18:00	Bore - Basalt East, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1130	8.1	29
SDB05B	21-Dec-2022 15:12:00	GROUNDWATER - CODISPOSAL	Bailer. Slightly turbid. Light brown/white colour. Organic odour. Fine particles. White particles. (Earthy odour). Bailed 6L.	7390	12.4	5
SDB06A	19-Dec-2022 15:18:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Nil odour. No particles. Water insufficient to pump. Bailed 6L.	1190	8.22	32
SDB06B	19-Dec-2022 15:31:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Cloudy sample. Clear colour. Nil odour. No particles.	976	8.64	23
SDB07A	19-Dec-2022 11:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1030	8.27	24
SDB07B	19-Dec-2022 11:33:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (earthy odour).	971	8.44	15
SDB08A	19-Dec-2022 12:38:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1720	8.08	34
SDB08B	19-Dec-2022 13:29:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. SWL and EC double checked and confirmed. (Earthy odour).	3510	12.2	12
T1	20-Dec-2022 14:12:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	6250	7.99	2510