

Site	Date	Other Tags	Comment_Field_Part 1	Electrical Conductivity (Lab) µS/cm	pH (Lab) pH	Sulfate(SO4 2-)_Turbidimetric mg/L
3067R	26-Jan-2023 13:48:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1810	7.97	1
3069R	26-Jan-2023 13:09:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2180	8.02	346
3072R	26-Jan-2023 12:30:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1180	7.9	47
CD01	26-Jan-2023 07:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	8680	7.89	2720
CD03	26-Jan-2023 08:36:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	6260	7.78	2550
CD04	26-Jan-2023 10:01:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1550	8.08	98
CD05	27-Jan-2023 12:21:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1300	8.15	37
CD06	25-Jan-2023 14:51:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Sulphur odour. No particles. SWL double checked and confirmed.	6280	7.81	2530
KS2A	27-Jan-2023 14:58:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Bailer. Cloudy sample. Clear colour. Nil odour. Organic particles. Insufficient water to pump. Bailed 4L (Due to running out of water).	1340	7.92	24
KS2B	27-Jan-2023 14:53:00	GROUNDWATER - CODISPOSAL	Bore bent. No sample collected. SWL only.			
NB1	26-Jan-2023 10:51:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1220	8.26	44
NB2	25-Jan-2023 14:10:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes. SWL double checked and confirmed.	6490	7.85	926
NB5	26-Jan-2023 11:53:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Bore blocked at approx. 1.2m. No sample collected. SWL double checked and confirmed.			
NF1A	26-Jan-2023 15:54:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1010	8.12	8
NF1B	26-Jan-2023 14:57:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	1240	7.95	17
NF2a	27-Jan-2023 13:25:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1020	8.06	58
NF3b	27-Jan-2023 13:05:00	GROUNDWATER - CODISPOSAL	Bailer. Cloudy sample. Clear colour. Nil odour. No particles. Bailed 12L.	1430	7.73	38
NS3	25-Jan-2023 08:18:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Cloudy sample. Clear colour. Nil odour. No particles.	1060	8.06	41
PB2	26-Jan-2023 09:56:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Pump in bore. Not pumping. No sample collected. SWL only.			
SA1	26-Jan-2023 11:51:00	GROUNDWATER - CODISPOSAL	Unsuccessful bailing bore. No water obtained. No sample collected. SWL only. SWL double checked and confirmed.			
SA2	26-Jan-2023 12:17:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Slight sulphur odour. Organic particles. Bailed 6L. SWL and EC double checked and confirmed.	6160	7.82	1740
SA6	26-Jan-2023 12:06:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	12400	7.7	3170
SA7	27-Jan-2023 14:47:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.80m. No sample collected.			
SDB05A	25-Jan-2023 15:38:00	Bore - Basalt East, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1010	8.06	29
SDB05B	25-Jan-2023 15:25:00	GROUNDWATER - CODISPOSAL	Bailer. Slightly turbid. White in colour. Slight organic odour. Fine particles. White particles. (Earthy odour). Bailed 6L.	7130	12.4	8
SDB06A	25-Jan-2023 12:59:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Nil odour. No particles. Water insufficient to pump. Bailed 6L.	1270	8.11	30
SDB06B	25-Jan-2023 13:17:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	982	8.49	24
SDB07A	25-Jan-2023 09:16:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1020	8.18	24
SDB07B	25-Jan-2023 09:59:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	999	8.41	13
SDB08A	25-Jan-2023 11:00:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	1980	7.98	39
SDB08B	25-Jan-2023 11:46:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. SWL double checked and confirmed.	2660	12.1	20
T1	26-Jan-2023 09:11:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	6030	7.54	2490