

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	11-Aug-2023 08:52:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only. No access point for LF pump or bailer. No sample collected.	125.33
300-MB04	9-Aug-2023 15:45:00	GROUNDWATER - BASAL SAND	Bailer. Not turbid. Clear colour. Nil odour. No particles. Insufficient water to pump. Bailed 6L.	56.37
300-MB11	9-Aug-2023 14:47:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	53.04
300-MB36	11-Aug-2023 08:09:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Orange particles.	51.35
301N	23-Aug-2023 12:01:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	No access for dipper. No SWL.	
3028D	16-Aug-2023 11:17:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.19
303	11-Aug-2023 08:29:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only. Tried to use bailer to obtain sample. No sample collected. 16.11.2023 - SWL corrected from 16.32m to 116.32m.	116.32
3045D	10-Aug-2023 13:41:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.82
3067R	7-Aug-2023 14:38:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	5.37
3069R	7-Aug-2023 13:50:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.5
3072R	3-Aug-2023 15:10:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.08
62641	8-Aug-2023 13:06:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Black colour. Strong organic odour. Fine particles. Black particles. Dead frog odour. Dipper probe and pump has dead frog looking slick over it. Pump stopped at 26m. Pumped at 22m.	12.19
CD01	2-Aug-2023 11:01:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.25
CD03	9-Aug-2023 08:28:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29.08
CD04	2-Aug-2023 14:27:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.17
CD05	2-Aug-2023 12:29:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.45
CD06	7-Aug-2023 11:12:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	13.19
KS1D	11-Aug-2023 09:25:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Tape stopped at approx. 27.53m.	
KS1F	11-Aug-2023 09:02:00	GROUNDWATER - BASAL SAND, Bore - Tertiary Basal Sand	Bailer. Turbid. White/grey colour. Nil odour. Fine particles. White particles. TD approx. 46m. Bailed 6L.	44.67
KS2A	11-Aug-2023 09:59:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only.	16.67
KS2B	11-Aug-2023 09:55:00	GROUNDWATER - CODISPOSAL	Bore bent. No sample collected. SWL only.	65.57
KS4A	23-Aug-2023 12:15:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Bore blocked at approx. 88m. No sample collected. SWL only.	161.78
MB1 RDH1357	9-Aug-2023 13:04:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.2
MB2 RDH1338	9-Aug-2023 11:06:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	47.43
MB3 RDH1097	3-Aug-2023 13:09:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Bore Label required.	37.9
MB4 RDH1336	9-Aug-2023 07:32:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Grey colour. Slight sulphur odour. Fine particles. Black particles. 50mm cap installed to stop frogs entering casing.	21.58
MB5 DDH435	3-Aug-2023 10:21:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. PD at 63m.	60.6
MB6 RDH1015	9-Aug-2023 09:06:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. 50mm cap installed to keep frogs out.	37.66
MB7 RDH1304	17-Aug-2023 10:49:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. Organic particles.	64.13
MB8 RDH1009	17-Aug-2023 12:03:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Turbid. Light brown colour. Nil odour. Fine particles. Brown particles. SWL double checked and confirmed.	9.66
NB1	2-Aug-2023 13:27:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.85
NB2	4-Aug-2023 11:27:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	16.45
NB5	23-Aug-2023 11:22:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Bore blocked at approx. 1.2m. No sample collected. SWL only.	5.82
NF1A	8-Aug-2023 12:08:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	14.12
NF1B	8-Aug-2023 11:01:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	19.02
NF2a	8-Aug-2023 14:07:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	21.67
NF3b	8-Aug-2023 15:21:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 12L.	20.65
NF5	10-Aug-2023 09:48:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Insufficient water to pump or bail. Tape stopped at approx. 18.09m. No sample collected.	27.65
NF6	10-Aug-2023 10:19:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Tape stopped at approx. 38m. Pumped at 35m.	19.61
NS3	4-Aug-2023 10:42:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.99
P1	11-Aug-2023 09:37:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Casing and plinth damaged/in ground. Prevents bail or pump. No sample collected. SWL only.	56.92
P2	9-Aug-2023 10:39:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Bailer. Turbid. Dark brown colour. Organic odour. Fine particles. Brown particles. SWL double checked and confirmed. Unable to get vehicle next to bore. Bailed 6L.	43.32
P3	8-Aug-2023 09:10:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Turbid. Grey colour. Nil odour. Fine particles. Black particles.	172.78
P4	7-Aug-2023 16:09:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Cloudy sample. Black colour. Sulphur odour. Fine particles. Black particles. EC double checked and confirmed. Hydrasleeve needs replacing.	136.4
PB2	9-Aug-2023 09:18:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Pump in bore. Not pumping. No sample collected. SWL only.	28.74
R1	10-Aug-2023 07:44:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	43.6
R10	3-Aug-2023 13:51:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Brown particles.	18.93
R11	23-Aug-2023 14:45:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	54.23
R12	16-Aug-2023 14:08:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.48
R13	16-Aug-2023 13:01:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	39.61
R14	16-Aug-2023 12:20:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.28
R15A	10-Aug-2023 12:45:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	12.2

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R16	16-Aug-2023 16:25:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.83
R17	9-Aug-2023 12:06:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Cloudy sample. Clear colour. Slight organic odour. No particles. Frogs blocking the bore. Could only pump at 70m.	55.58
R18A	10-Aug-2023 11:22:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. Organic particles.	16.03
R2	3-Aug-2023 12:02:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Slightly turbid. Yellow/brown colour. Nil odour.	38.85
R3	10-Aug-2023 12:10:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	30.9
R4	23-Aug-2023 10:30:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	33.47
R5	2-Aug-2023 13:44:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. Organic particles. White particles. Some organic brown particles.	13.21
R6	2-Aug-2023 11:20:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. Organic particles. Brown particles.	27.93
R7A	3-Aug-2023 09:08:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Black particles. Few brown particles present.	37.55
R7B	3-Aug-2023 08:10:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Turbid. Black colour. Nil odour. Fine particles. Black particles. New bore label required. Obstruction of dipper tape at 59m.	59.78
R8	10-Aug-2023 08:58:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. 251_QAQCD03 Taken- Yes. SWL checked with two dip tapes and confirmed.	42.23
R9	10-Aug-2023 11:03:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles.	31.99
SA1	23-Aug-2023 11:30:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump or bail. No sample collected. SWL only.	7.83
SA2	3-Aug-2023 15:55:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. Organic particles. Bailed 6L.	3.41
SA6	3-Aug-2023 16:26:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	2.07
SA7	3-Aug-2023 16:11:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.8m. No sample collected.	
SDB01A	9-Aug-2023 10:14:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.04
SDB03B	16-Aug-2023 15:03:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD05 Taken- Yes.	24.95
SDB05A	8-Aug-2023 09:43:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.35
SDB05B	8-Aug-2023 09:28:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Organic odour. Fine particles. White particles. (Earthy odour). Insufficient water to pump. Bailed 6L.	39.24
SDB06A	8-Aug-2023 16:09:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Organic odour. No particles. Insufficient water to pump. Bailed 12L.	28.33
SDB06B	8-Aug-2023 16:15:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	36.36
SDB07A	9-Aug-2023 11:20:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	17.26
SDB07B	8-Aug-2023 08:22:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. Earthy odour.	17.09
SDB08A	9-Aug-2023 12:24:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.63
SDB08B	9-Aug-2023 13:19:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy odour).	27.86
T1	2-Aug-2023 15:18:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.5