

				Electrical			Sulfate(SO4 2-
				Conductivity			)_Turbidimetric
Site	Date	Other Tags	Comment_Field_Part 1	(Lab) µS/cm	pH (Lab) pH	mg/L	
3067R	18-Oct-2023 10:07:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2740	7.73	486	
3069R	18-Oct-2023 10:46:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2700	7.92	397	
3072R	18-Oct-2023 09:05:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1270	8.03	40	
CD01	16-Oct-2023 14:24:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	9240	7.64	3240	
CD03	16-Oct-2023 13:41:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6160	7.46	2500	
CD04	16-Oct-2023 11:46:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1550	7.97	40	
CD05	16-Oct-2023 10:41:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1360	8.02	36	
CD06	17-Oct-2023 10:12:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	6910	7.34	3070	
KS2A	18-Oct-2023 13:38:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only.				
KS2B	18-Oct-2023 13:43:00	GROUNDWATER - CODISPOSAL	SWL only. Bore bent. No sample collected.				
NB1	16-Oct-2023 11:13:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1440	8.04	82	
NB2	3-Oct-2023 12:52:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251 QAQCD01 Taken- Yes.	5460	8.03	890	
NB5	18-Oct-2023 13:11:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	SWL only. Insufficient water to obtain a sample. Access needs improvement.				
NF1A	17-Oct-2023 07:37:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1040	7.65	7	
NF1B	17-Oct-2023 06:48:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251 QAQCD02 Taken- Yes.	1430	7.59	23	
NF2a	16-Oct-2023 09:19:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1170	8	66	
NF3b	16-Oct-2023 10:02:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. Note change in pH.	1600	8.09	37	
NS3	3-Oct-2023 13:43:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Collected an extra litre to confirm EC.	1120	8.3	22	
PB2	16-Oct-2023 12:47:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	SWL only. Pump not operating at time of visit - no sample taken.				
SA1	18-Oct-2023 13:10:00	GROUNDWATER - CODISPOSAL	SWL only. Insufficient water to obtain a representative sample. Access needs improvement.				
SA2	18-Oct-2023 08:26:00	GROUNDWATER - CODISPOSAL	Dry. Tape stopped at 4.73m.				
SA6	18-Oct-2023 08:41:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6Lt.	8930	7.92	1720	
SA7	18-Oct-2023 08:15:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.8m. No sample collected.				
SDB05A	17-Oct-2023 08:32:00	Bore - Basalt East, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL checked and confirmed.	1140	7.92	29	
SDB05B	17-Oct-2023 09:09:00	GROUNDWATER - CODISPOSAL	Bailer. Cloudy sample. Grey colour. Organic odour. Fine particles. White particles. Repeated bailing to confirm EC.	7600	12.4	7	
SDB06A	3-Oct-2023 14:57:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1350	8.45	22	
SDB06B	17-Oct-2023 15:42:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1040	8.22	29	
SDB07A	17-Oct-2023 15:02:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Extra volume pumped to confirm readings.	1100	8.2	25	
SDB07B	17-Oct-2023 13:23:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles. pH meter checked against standards in field and confirmed correct.	1050	8.36	13	
SDB08A	17-Oct-2023 11:28:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2310	7.84	41	
SDB08B	17-Oct-2023 12:16:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles.	3700	12.1	17	
T1	16-Oct-2023 12:55:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Extra volume pumped to confirm EC.	4420	7.34	1520	