

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	28-Feb-2024 11:58:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL double checked and confirmed. No access for pump or bailer. No sample collected. SWL only.	121.67
300-MB04	26-Feb-2024 11:56:00	GROUNDWATER - BASAL SAND	Bailer. Turbid. Black colour. Strong sulphur odour. Organic particles. Insufficient water to pump. Bailed 6L.	56.21
300-MB11	26-Feb-2024 11:00:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	52.85
300-MB36	26-Feb-2024 12:48:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Orange particles.	51.15
3028D	27-Feb-2024 07:46:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	29.26
303	22-Feb-2024 08:50:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Unsuccessful bailing bore. No sample collected. SWL only.	112.44
3045D	20-Feb-2024 10:27:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.87
3067R	8-Feb-2024 14:39:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	4.48
3069R	8-Feb-2024 13:30:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.29
3072R	8-Feb-2024 15:21:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.11
62641	13-Feb-2024 12:52:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Black colour. Strong organic odour. Fine particles. Black particles. Dead animal odour.	12.48
CD01	6-Feb-2024 09:03:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.58
CD03	6-Feb-2024 10:17:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29.23
CD04	6-Feb-2024 13:34:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.03
CD05	13-Feb-2024 15:26:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.65
CD06	8-Feb-2024 08:01:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	13.54
KS1D	26-Feb-2024 14:01:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Tape stopped at approx. 27.55m.	
KS1F	26-Feb-2024 13:45:00	GROUNDWATER - BASAL SAND, Bore - Tertiary Basal Sand	Bailer. Turbid. White/pink in colour. Nil odour. Fine particles. White particles. Insufficient water to pump. Bailed 4L. Bailer not full each time. Close to bottom.	45.05
KS2A	20-Feb-2024 09:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only.	16.66
KS2B	20-Feb-2024 09:38:00	GROUNDWATER - CODISPOSAL	Bore bent. No sample collected. SWL only.	65.51
MB1 RDH1357	27-Feb-2024 14:26:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.68
MB2 RDH1338	21-Feb-2024 09:52:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	47.5
MB3 RDH1097	21-Feb-2024 11:19:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.97
MB4 RDH1336	21-Feb-2024 13:59:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Grey colour. Slight sulphur odour. Fine particles. Black particles.	21.51
MB5 DDH435	12-Feb-2024 11:51:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	60.66
MB6 RDH1015	21-Feb-2024 12:13:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Cloudy sample. Light brown colour. Nil odour. No particles. 50mm plug has been removed by cattle. Could not be located.	37.72
MB7 RDH1304	19-Feb-2024 14:54:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	64.23
MB8 RDH1009	21-Feb-2024 14:58:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles.	16.4
NB1	6-Feb-2024 14:37:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	21.06
NB2	7-Feb-2024 10:46:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	16.57
NB5	28-Feb-2024 10:48:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL double checked and confirmed. Bore blocked at approx. 1.2m. No sample collected, SWL only.	5.9
NF1A	13-Feb-2024 10:55:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	14.54
NF1B	13-Feb-2024 11:37:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	19.73
NF2a	13-Feb-2024 13:48:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.95
NF3b	13-Feb-2024 14:49:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 12L.	20.69
NF5	28-Feb-2024 12:50:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	No water obtained in bailer. No sample collected, SWL only.	26.29
NF6	20-Feb-2024 10:17:00	GROUNDWATER - BASALT, Bore - Basalt East	Unable to pump or bail. Pump almost stuck at approx. 8m. Tried to bail, same issue. No sample collected. SWL only.	21.12
NS3	7-Feb-2024 09:26:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.73
P1	26-Feb-2024 14:15:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Casing and plinth damaged in ground. Prevents bailer and pump. No sample collected, SWL only.	57.6
P2	6-Feb-2024 13:04:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Turbid. Dark brown colour. Sulphur odour. Fine particles. Black particles. Unable to get light vehicle next to bore. Bailer used. Bailed 6L.	45.2
P3	28-Feb-2024 08:27:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Turbid. Black colour. Slight sulphur odour. Fine particles. Black particles. Organic particles.	172.5
P4	28-Feb-2024 10:07:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Not turbid. Clear colour. Sulphur odour. Fine particles. Black particles. SWL and EC double checked and confirmed. Hydrasleeve replaced.	132.14
PB2	6-Feb-2024 11:47:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Pump in bore. Not operating. SWL only, no sample collected.	29.23
R1	12-Feb-2024 08:26:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Pumped extra to check pH. Confirmed.	43.41
R10	27-Feb-2024 15:25:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.75
R11	26-Feb-2024 15:40:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	54.4

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R12	5-Feb-2024 15:21:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.54
R13	27-Feb-2024 13:27:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	40.11
R14	27-Feb-2024 09:26:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	20.04
R15A	20-Feb-2024 12:36:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	12.04
R16	19-Feb-2024 11:01:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.88
R17	21-Feb-2024 07:18:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Cloudy sample. Light brown colour. Slight organic odour. No particles. Blockage at 64m. Pumped at 64m. Slow pump rate.	55.75
R18A	20-Feb-2024 13:44:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. Organic particles.	16.13
R2	12-Feb-2024 13:11:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.9
R3	28-Feb-2024 10:25:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.9
R4	27-Feb-2024 12:54:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	33.51
R5	26-Feb-2024 12:37:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. Organic particles. Brown particles.	13.3
R6	19-Feb-2024 09:57:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.92
R7A	12-Feb-2024 10:02:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.91
R7B	12-Feb-2024 10:42:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Cloudy sample. Grey colour. Nil odour. No particles. Extra volume pumped to confirm EC readings. Checked probe with 1413 standard and confirmed OK.	59.85
R8	28-Feb-2024 14:52:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. 251_QAQCD03 Taken- Yes. SWL checked and confirmed.	37.4
R9	28-Feb-2024 12:45:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Bailer. Slightly turbid. Light brown colour. Nil odour. Coarse particles. Black particles. Previous gate from Banyula fenced shut. No access via It'll Do. Referred to Kestrel . Could not use LF pump, disposable bailer used.	31.61
SA1	28-Feb-2024 10:52:00	GROUNDWATER - CODISPOSAL	Insufficient water to sample. No sample collected. SWL only.	7.85
SA2	9-Feb-2024 09:32:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	2.38
SA6	9-Feb-2024 09:12:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1.76
SA7	9-Feb-2024 09:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.8m. No sample collected.	
SDB01A	21-Feb-2024 08:43:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.93
SDB03B	5-Feb-2024 14:23:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD05 Taken- Yes.	25.05
SDB05A	13-Feb-2024 09:35:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.78
SDB05B	13-Feb-2024 08:56:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Organic odour. Fine particles. White particles. (Earthy odour). Bailed 12L.	38.53
SDB06A	8-Feb-2024 11:38:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Organic odour. No particles. Bailed 12L. (Earthy odour).	28.71
SDB06B	8-Feb-2024 11:53:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	36.17
SDB07A	7-Feb-2024 11:51:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	17.56
SDB07B	7-Feb-2024 12:34:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	17.43
SDB08A	7-Feb-2024 13:40:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.91
SDB08B	7-Feb-2024 14:51:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	27.99
T1	6-Feb-2024 11:03:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.74