

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	5-Aug-2024 11:29:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	No access for pump or bailer. SWL only. Ontoto logger updated.	113.74
300-MB04	27-Aug-2024 09:50:00	GROUNDWATER - BASAL SAND	Bailer. Slightly turbid. Grey colour. Strong sulphur odour. Fine particles. Black particles. Organic particles. Insufficient water to pump. Bail	56.2
300-MB11	27-Aug-2024 08:31:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	52.77
300-MB36	20-Aug-2024 09:44:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Air in lines. Conductivity re-calibrated at 6th line.	51.13
301N	28-Aug-2024 13:01:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	No access for dipper tape. No SWL obtained.	
3028D	27-Aug-2024 13:34:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL double checked and confirmed.	37.97
303	23-Aug-2024 15:11:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Logger updated. Unsuccessful bailing bore. No sample collected. SWL only.	105.26
3045D	20-Aug-2024 14:01:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.25
3067R	8-Aug-2024 11:49:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	5.64
3069R	8-Aug-2024 12:36:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.26
3072R	8-Aug-2024 13:50:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.67
62641	9-Aug-2024 10:36:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. Fine particles. Black particles.	12.68
CD01	8-Aug-2024 09:16:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	19.93
CD03	22-Aug-2024 11:44:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29
CD04	22-Aug-2024 08:13:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.6
CD05	22-Aug-2024 14:16:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.44
CD06	5-Aug-2024 15:08:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	14.18
KS1D	20-Aug-2024 12:18:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Tape stopped at 27.8m.	
KS1F	20-Aug-2024 09:03:00	GROUNDWATER - BASAL SAND, Bore - Tertiary Basal Sand	Insufficient water to pump. Attempted to bail, insufficient water to bail. Mud on SWL and bailer.	45.36
KS2A	20-Aug-2024 08:06:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only.	16.69
KS2B	20-Aug-2024 08:08:00	GROUNDWATER - CODISPOSAL	Dry. Bore bent. No sample collected. Ants nest in casing. Hit bottom at 66.85m. Photos taken.	
KS4A	28-Aug-2024 13:16:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Bore blocked at approx. 120.75m. Bore possibly collapsed. No sample collected.	
MB1 RDH1357	9-Aug-2024 11:47:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.85
MB2 RDH1338	10-Aug-2024 11:34:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	47.41
MB3 RDH1097	10-Aug-2024 09:47:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.15
MB4 RDH1336	10-Aug-2024 07:40:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	21.55
MB5 DDH435	5-Aug-2024 14:45:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. LF pump stopped at 64m. Set pump at 63m.	60.77
MB6 RDH1015	10-Aug-2024 08:41:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles.	37.82
MB7 RDH1304	28-Aug-2024 08:49:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	64.45
MB8 RDH1009	28-Aug-2024 10:04:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Slightly turbid. Light brown colour. Slight sulphur odour. No particles. SWL double checked and confirmed.	23.51
NB1	22-Aug-2024 09:15:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.86
NB2	5-Aug-2024 13:42:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes. EC double checked and confirmed.	17.37
NB5	26-Aug-2024 12:36:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Bore blocked at approx. 1.2m. SWL only, no sample collected.	6.5
NF1A	9-Aug-2024 08:05:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.08
NF1B	9-Aug-2024 09:15:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	20.31
NF2a	9-Aug-2024 11:34:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.27
NF3b	9-Aug-2024 12:30:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Slight sulphur odour. No particles. Bailed 12L.	20.73
NF5	20-Aug-2024 12:53:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Unable to get bailer down. No sample collected. SWL only.	26.14
NF6	20-Aug-2024 13:40:00	GROUNDWATER - BASALT, Bore - Basalt East	Bailer got stuck in bore, no sample collected. SWL only.	22.32
NS3	5-Aug-2024 12:55:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.69
P1	20-Aug-2024 08:47:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Casing and plinth damaged in ground. Preventing bailer and pump. No sample collected. SWL only.	57.79
P2	22-Aug-2024 13:41:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Bailer. Turbid. Dark brown colour. Slight sulphur odour. Fine particles. Black particles. Unable to get vehicle next to bore to pump. Bailed 6	44.98
P3	23-Aug-2024 09:40:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Turbid. Black colour. Sulphur odour. Fine particles. Black particles. Organic particles. SWL double checked and confirmed.	171.11
P4	23-Aug-2024 10:14:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve has ripped due to sharp points in bore. Tried to bail unsuccessful due to particles and depth of bore. New hydrasleeve installed	125.38
PB2	22-Aug-2024 10:18:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Pump in bore. SWL only. No sample collected.	28.77
R1	5-Aug-2024 11:26:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	43.26
R10	6-Aug-2024 12:41:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.61
R11	8-Aug-2024 09:51:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	54.73
R12	9-Aug-2024 12:26:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.51
R13	10-Aug-2024 14:53:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	40.02

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R14	28-Aug-2024 15:36:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. pH and SWL double checked and confirmed.	22.43
R15A	20-Aug-2024 15:01:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	12.03
R16	28-Aug-2024 07:49:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	20.95
R17	10-Aug-2024 12:33:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. Fine particles. Brown particles. Pumped at 64m. pH checked and confirmed.	56.04
R18A	27-Aug-2024 11:00:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.33
R2	5-Aug-2024 15:53:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	38.9
R3	6-Aug-2024 10:16:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.97
R4	8-Aug-2024 09:04:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	33.7
R5	9-Aug-2024 08:49:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	13.49
R6	9-Aug-2024 07:12:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.89
R7A	5-Aug-2024 12:40:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.64
R7B	5-Aug-2024 13:28:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. No particles.	59.8
R8	6-Aug-2024 09:04:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. 251_QAQCD03 Taken- No. SWL checked 3 times and confirm	39.27
R9	1-Aug-2024 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Access restricted. Site access not authorised. Notified by Kestrel 18.07.2024.	
SA1	26-Aug-2024 12:40:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump or bail. SWL only, no sample collected.	8.41
SA2	8-Aug-2024 14:48:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. Organic particles. Bailed 6L.	3.35
SA6	8-Aug-2024 11:22:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L.	1.91
SA7	8-Aug-2024 15:02:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.80m. No sample collected.	
SDB01A	10-Aug-2024 10:31:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.95
SDB03B	10-Aug-2024 13:56:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD05 Taken- Yes.	25.24
SDB05A	23-Aug-2024 08:08:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.44
SDB05B	23-Aug-2024 07:41:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Strong organic odour. No particles. (Earthy odour). Bailed 12L.	38.97
SDB06A	6-Aug-2024 14:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Nil odour. No particles. Insufficient water to pump. Bailed 12L then sampled.	28.84
SDB06B	6-Aug-2024 14:18:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	36.13
SDB07A	6-Aug-2024 09:16:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18
SDB07B	6-Aug-2024 10:14:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour).	17.86
SDB08A	6-Aug-2024 11:33:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.78
SDB08B	6-Aug-2024 12:38:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour). EC climbing, double checked and confirmed.	27.86
T1	22-Aug-2024 10:33:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.51