

Site	Date	Other Tags	Comment_Field_Part 1	Electrical Conductivity (Lab) µS/cm	pH (Lab) pH	Sulfate(SO4 2-)_Turbidimetric mg/L
3067R	25-Feb-2025 11:38:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	4550	7.48	821
3069R	25-Feb-2025 10:14:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	2870	7.79	468
3072R	25-Feb-2025 09:06:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	1240	7.81	49
CD01	4-Feb-2025 08:30:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	9050	7.73	3200
CD03	4-Feb-2025 10:05:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	5640	7.74	2360
CD04	26-Feb-2025 10:43:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1730	7.83	37
CD05	14-Feb-2025 13:10:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1310	7.72	26
CD06	11-Feb-2025 11:32:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC Double checked and confirmed.	6450	7.77	2690
KS2A	25-Feb-2025 08:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only. Insufficient water for LF pump. Tried to bail but after 2L bore dry and no recharge.			
KS2B	25-Feb-2025 08:45:00	GROUNDWATER - CODISPOSAL	Dry. Bore completely blocked by ant/termite nest. Removed the ant nest. Bore blocked, taped stopped at approx. 65.16m. Photo taken.			
NB1	26-Feb-2025 12:53:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1440	8.11	56
NB2	11-Feb-2025 15:16:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	5850	7.88	889
NB5	26-Feb-2025 08:48:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. Casing height has changed 0.59m. Air in lines at 9:27am.	1020	7.78	385
NF1A	14-Feb-2025 08:08:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1030	7.81	6
NF1B	14-Feb-2025 09:49:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	1390	7.80	14
NF2a	13-Feb-2025 14:26:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Air in lines of pump. Slow to start.	1140	8.10	36
NF3b	14-Feb-2025 12:22:00	GROUNDWATER - CODISPOSAL	Bailer. Slightly turbid. Light brown colour. Nil odour. Fine particles. White particles. Bailed 12L then sampled.	1560	7.40	26
NS3	12-Feb-2025 08:15:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1060	8.19	19
PB2	4-Feb-2025 12:20:00	Bore - Tertiary Basalt, GROUNDWATER - CODISPOSAL	SWL only. Pump in bore. Not Pumping. SWL only, No sample collected.			
SA1	26-Feb-2025 08:33:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump or bail. No sample collected.			
SA2	25-Feb-2025 08:36:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. White particles. Bailed 3L then sampled. EC and SWL double checked and confirmed.	11300	7.48	2730
SA6	25-Feb-2025 08:14:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 3L then sampled.	8890	7.71	1570
SA7	25-Feb-2025 07:08:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx 1.80m. No sample collected.			
SDB05A	13-Feb-2025 11:48:00	Bore - Basalt East, GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1140	7.72	30
SDB05B	13-Feb-2025 11:34:00	GROUNDWATER - CODISPOSAL	SWL 41.14m, bore depth 42.7, leaving 1.56m of water. Insufficient water for pumping. Attempted bailing 2L; only 40ml recovered. Unable to bail due to low water levels.			
SDB06A	12-Feb-2025 10:55:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. Grey particles. Insufficient water to pump. Bailed 12L then sampled.	1360	8.09	20
SDB06B	12-Feb-2025 09:57:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	866	8.45	21
SDB07A	12-Feb-2025 14:02:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1020	8.33	22
SDB07B	12-Feb-2025 12:54:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	1040	8.48	14
SDB08A	12-Feb-2025 15:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	2210	8.05	35
SDB08B	13-Feb-2025 09:02:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Increased time between recharge cycle. Drawdown was dropping at a fast rate. EC double checked and confirmed.	1350	11.60	21
T1	4-Feb-2025 11:13:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	4780	7.93	1810