

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	27-Feb-2025 11:08:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	No access for pump or bailer. Ontoto logger updated. SWL only, no sample collected.	111.87
300-MB04	25-Feb-2025 11:02:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Pumped at 58m Hydrasleeve recommended for this site. Extra volume pumped to check pH.	56.09
300-MB11	25-Feb-2025 10:23:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Slightly turbid. Yellow/brown colour. Nil odour. No particles. pH checked against standard and confirmed OK.	52.62
300-MB36	25-Feb-2025 09:26:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	51.00
301N	27-Feb-2025 11:35:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	No access for dipper tape. No SWL obtained.	
3028D	25-Feb-2025 13:59:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Turbid. Dark brown colour. Nil odour. Fine particles. Brown particles. Pumped at 55m. Pump stopped at 57m. Gas drainage station nearby.	42.49
303	27-Feb-2025 10:39:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL double checked and confirmed. Unsuccessful bailing. Hydrasleeve installed as discussed with Kestrel Environmental team. To be collected next monitoring round. No sample collected.	103.98
3045D	26-Feb-2025 12:23:00	GROUNDWATER - BASAL SAND	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	23.30
3067R	25-Feb-2025 11:38:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	3.62
3069R	25-Feb-2025 10:14:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	15.24
3072R	25-Feb-2025 09:06:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Overgrown. Grass needs to be slashed.	6.50
62641	25-Feb-2025 12:57:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Grey colour. Nil odour. Fine particles. Black particles. Pumped at 25 - pump would not lower further.	12.98
CD01	4-Feb-2025 08:30:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.83
CD03	4-Feb-2025 10:05:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29.35
CD04	26-Feb-2025 10:43:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.54
CD05	14-Feb-2025 13:10:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.69
CD06	11-Feb-2025 11:32:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC Double checked and confirmed.	14.46
KS1D	25-Feb-2025 09:12:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Tape stopped at 27.5m.	
KS1F	25-Feb-2025 09:14:00	GROUNDWATER - BASAL SAND, Bore - Tertiary Basal Sand	Dry. Tape stopped at 45.53m.	
KS2A	25-Feb-2025 08:40:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only. Insufficient water for LF pump. Tried to bail but after 2L bore dry and no recharge.	16.68
KS2B	25-Feb-2025 08:45:00	GROUNDWATER - CODISPOSAL	Dry. Bore completely blocked by ant/termite nest. Removed the ant nest. Bore blocked, taped stopped at approx. 65.16m. Photo taken.	
KS4A	25-Feb-2025 12:17:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Bore blocked at 120.72m. No sample taken.	
MB1 RDH1357	27-Feb-2025 14:01:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	39.20
MB2 RDH1338	21-Feb-2025 08:58:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	47.74
MB3 RDH1097	19-Feb-2025 07:48:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Track requires mowing.	38.22
MB4 RDH1336	19-Feb-2025 06:47:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Access track badly overgrown. Urgently needs slashing/grading.	21.59
MB5 DDH435	18-Feb-2025 10:12:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Extra volume pumped to check pH. pH checked against standard and confirmed OK.	60.89
MB6 RDH1015	19-Feb-2025 08:56:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Track needs slashing.	37.96
MB7 RDH1304	21-Feb-2025 14:31:00	GROUNDWATER - PERMIAN	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	64.52
MB8 RDH1009	27-Feb-2025 15:43:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	30.17
NB1	26-Feb-2025 12:53:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	21.12
NB2	11-Feb-2025 15:16:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes.	17.57
NB5	26-Feb-2025 08:48:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. Casing height has changed 0.59m. Air in lines at 9:27am.	6.49
NF1A	14-Feb-2025 08:08:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.32
NF1B	14-Feb-2025 09:49:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	20.79
NF2a	13-Feb-2025 14:26:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Air in lines of pump. Slow to start.	23.35
NF3b	14-Feb-2025 12:22:00	GROUNDWATER - CODISPOSAL	Bailer. Slightly turbid. Light brown colour. Nil odour. Fine particles. White particles. Bailed 12L then sampled.	20.78
NF5	26-Feb-2025 06:50:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only. LF pump jammed at about 30m and lost in bore. No sample collected.	26.17
NF6	26-Feb-2025 13:12:00	GROUNDWATER - BASALT, Bore - Basalt East	SWL only. Bailer would not go down bore. No sample collected.	23.18
NS3	12-Feb-2025 08:15:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.60
P1	25-Feb-2025 09:01:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only. Bore casing damaged - not able to deploy any sampling equipment.	57.80
P2	26-Feb-2025 12:07:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Bailer. Slightly turbid. Light brown colour. Organic odour. Coarse particles. Brown particles. Unable to get vehicle next to bore to pump. Bailed 6L then sampled.	44.93
P3	27-Feb-2025 08:38:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Turbid. Black colour. Slight sulphur odour. Fine particles. Black particles.	169.02
P4	27-Feb-2025 08:11:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Hydrasleeve. Not turbid. Clear colour. Sulphur odour. Fine particles. Black particles.	124.08
PB2	4-Feb-2025 12:20:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only. Pump in bore. Not Pumping. SWL only, No sample collected.	28.91

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R1	18-Feb-2025 07:38:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. No monument cap.	43.31
R10	19-Feb-2025 11:43:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.42
R11	19-Feb-2025 13:30:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	54.94
R12	27-Feb-2025 07:09:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.55
R13	27-Feb-2025 08:08:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	40.20
R14	27-Feb-2025 09:30:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Bore blocked at approx. 26.5m due to frogs. Unable to pump or bail. No sample collected. SWL only and double checked. To be re-attempted in March 2025.	25.96
R15A	26-Feb-2025 11:07:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	12.12
R16	21-Feb-2025 13:43:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	21.02
R17	21-Feb-2025 06:47:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. Fine particles. Brown particles.	56.32
R18A	26-Feb-2025 10:08:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	16.48
R2	18-Feb-2025 11:27:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	39.00
R3	27-Feb-2025 13:55:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. First attempt on 19/2/25 - Belcong creek was still flooding and fences across road.	31.05
R4	20-Feb-2025 09:06:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	33.82
R5	27-Feb-2025 08:41:00	GROUNDWATER - BASALT, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	13.65
R6	27-Feb-2025 06:55:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	27.90
R7A	18-Feb-2025 08:46:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	37.57
R7B	18-Feb-2025 09:28:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Turbid. Dark grey Nil odour. No particles.	59.70
R8	18-Feb-2025 13:41:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. 251_QAQCD03 Taken- Yes.SWL checked twice and confirmed. pH rechecked against standards and confirmed OK.	43.49
R9	1-Feb-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Not Scheduled.	
SA1	26-Feb-2025 08:33:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump or bail. No sample collected.	8.27
SA2	25-Feb-2025 08:36:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. White particles. Bailed 3L then sampled. EC and SWL double checked and confirmed.	1.84
SA6	25-Feb-2025 08:14:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 3L then sampled.	1.94
SA7	25-Feb-2025 07:08:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx 1.80m. No sample collected.	
SDB01A	21-Feb-2025 07:48:00	GROUNDWATER - BASALT, Bore - Basalt West	Low Flow Pump. Not turbid. Clear colour. Slight sulphur odour. No particles.	31.00
SDB03B	21-Feb-2025 10:33:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD05 Taken- Yes.	25.45
SDB05A	13-Feb-2025 11:48:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.79
SDB05B	13-Feb-2025 11:34:00	GROUNDWATER - CODISPOSAL	SWL 41.14m, bore depth 42.7, leaving 1.56m of water. Insufficient water for pumping. Attempted bailing 2L; only 40ml recovered. Unable to bail due to low water levels.	41.14
SDB06A	12-Feb-2025 10:55:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. Grey particles. Insufficient water to pump. Bailed 12L then sampled.	28.88
SDB06B	12-Feb-2025 09:57:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	36.04
SDB07A	12-Feb-2025 14:02:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.33
SDB07B	12-Feb-2025 12:54:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.27
SDB08A	12-Feb-2025 15:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.79
SDB08B	13-Feb-2025 09:02:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. Increased time between recharge cycle. Drawdown was dropping at a fast rate. EC double checked and confirmed.	28.13
T1	4-Feb-2025 11:13:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	24.73