

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
202	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
300-MB04	6-Mar-2025 14:48:00	GROUNDWATER - BASAL SAND	SWL only.	56.06
300-MB11	6-Mar-2025 14:37:00	GROUNDWATER - BASAL SAND	SWL only.	52.46
300-MB36	6-Mar-2025 14:16:00	GROUNDWATER - BASAL SAND	SWL only.	50.85
301N	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
3028D	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Not Scheduled.	
303	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
3045D	26-Mar-2025 07:41:00	GROUNDWATER - BASAL SAND	SWL only.	23.38
3067R	6-Mar-2025 10:34:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. SWL and EC double checked and confirmed.	4.02
3069R	6-Mar-2025 09:23:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.20
3072R	6-Mar-2025 08:17:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	6.54
62641	5-Mar-2025 11:34:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	SWL only.	12.05
CD01	5-Mar-2025 08:04:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	19.69
CD03	5-Mar-2025 10:00:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	29.26
CD04	5-Mar-2025 12:05:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	30.31
CD05	5-Mar-2025 13:41:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	22.71
CD06	4-Mar-2025 07:01:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	14.52
KS1D	6-Mar-2025 14:27:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Dry. Tape stopped at approx. 27.53m.	
KS1F	6-Mar-2025 14:23:00	GROUNDWATER - BASAL SAND, Bore - Tertiary Basal Sand	Dry. Tape stopped at approx. 45.51m.	
KS2A	6-Mar-2025 13:54:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	SWL only.	16.66
KS2B	6-Mar-2025 13:50:00	GROUNDWATER - CODISPOSAL	Dry. Tape stopped at approx. 65.11m. No sample collected. Ants nest at top of casing.	
KS4A	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
MB1 RDH1357	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN	Not Scheduled.	
MB2 RDH1338	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN	Not Scheduled.	
MB3 RDH1097	6-Mar-2025 11:06:00	GROUNDWATER - BASALT, Bore - Basalt West	SWL only.	38.20
MB4 RDH1336	6-Mar-2025 11:19:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	SWL only. Access track hazardous - urgently needs slashing.	21.56
MB5 DDH435	6-Mar-2025 12:17:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only.	60.84
MB6 RDH1015	6-Mar-2025 10:55:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only.	37.98
MB7 RDH1304	26-Mar-2025 13:32:00	GROUNDWATER - PERMIAN	SWL only.	64.48
MB8 RDH1009	26-Mar-2025 14:13:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only. SWL checked and confirmed.	35.34
NB1	5-Mar-2025 13:04:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	21.10
NB2	4-Mar-2025 09:33:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD01 Taken- Yes. EC double checked and confirmed.	17.63
NB5	6-Mar-2025 12:07:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Slightly turbid. Light brown colour. Nil odour. No particles. EC checked and confirmed.	6.54
NF1A	5-Mar-2025 13:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	15.33
NF1B	5-Mar-2025 11:43:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. 251_QAQCD02 Taken- Yes.	20.86
NF2a	5-Mar-2025 14:17:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Slightly turbid. Clear colour. Nil odour. No particles. Water from bore was brown and very turbid for the first 11L.	23.43
NF3b	6-Mar-2025 06:40:00	GROUNDWATER - CODISPOSAL	Bailer. Slightly turbid. Light brown colour. Nil odour. No particles. Bailed 12L then Sampled.	20.75
NF5	26-Mar-2025 07:21:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Pump jammed in bore. Tape stopped at 21.30m. Monument leaning.	
NF6	26-Mar-2025 07:30:00	GROUNDWATER - BASALT, Bore - Basalt East	SWL only.	23.23
NS3	4-Mar-2025 08:20:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	31.66
P1	6-Mar-2025 14:08:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	SWL only.	58.15
P2	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
P3	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
P4	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian GC seam	Not Scheduled.	
PB2	5-Mar-2025 11:47:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Pump in bore. Not pumping. SWL only, no sample collected.	28.92
R1	6-Mar-2025 13:12:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	SWL only.	43.39
R10	6-Mar-2025 10:05:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	SWL only.	18.39
R11	6-Mar-2025 09:42:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only.	54.95
R12	26-Mar-2025 11:01:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	SWL only.	25.57
R13	26-Mar-2025 10:53:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only.	40.37

Site	Date	Other Tags	Comment_Field_Part 1	Standing Water Level (SWL) mTOC
R14	26-Mar-2025 09:48:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. Slight dead animal smell.	26.08
R15A	26-Mar-2025 08:11:00	GROUNDWATER - BASALT, Bore - Basalt East	SWL only. Access track needs to be slashed.	12.12
R16	26-Mar-2025 13:27:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	SWL only.	21.01
R17	26-Mar-2025 12:15:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only.	56.34
R18A	26-Mar-2025 08:00:00	GROUNDWATER - BASALT, Bore - Basalt East	SWL only. Track need to be slashed.	16.46
R2	6-Mar-2025 12:00:00	GROUNDWATER - BASALT, Bore - Basalt West	SWL only. Access track needs to be mowed.	38.96
R3	6-Mar-2025 10:24:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	SWL only.	31.02
R4	25-Mar-2025 09:51:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only.	33.86
R5	6-Mar-2025 07:06:00	GROUNDWATER - BASALT, Bore - Basalt East	SWL only.	13.62
R6	6-Mar-2025 06:47:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only.	27.89
R7A	6-Mar-2025 12:30:00	GROUNDWATER - BASALT, Bore - Tertiary Basalt	SWL only.	37.47
R7B	6-Mar-2025 12:44:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	SWL only.	59.69
R8	6-Mar-2025 11:45:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	SWL only. 251_QAQCD03 Taken- No.	43.95
R9	1-Mar-2025 00:02:00	GROUNDWATER - PERMIAN, Bore - Permian sandstone	Not Scheduled.	
SA1	6-Mar-2025 12:04:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump or bail. No sample collected.	8.24
SA2	6-Mar-2025 07:57:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. Fine particles. White particles. Bailed 6L. EC double checked and confirmed.	2.14
SA6	6-Mar-2025 11:45:00	GROUNDWATER - CODISPOSAL	Bailer. Not turbid. Clear colour. Nil odour. No particles. Bailed 6L then sampled.	1.81
SA7	6-Mar-2025 07:47:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Dry. Tape stopped at approx. 1.80m.	
SDB01A	26-Mar-2025 11:47:00	GROUNDWATER - BASALT, Bore - Basalt West	SWL only.	30.91
SDB03B	26-Mar-2025 12:34:00	GROUNDWATER - BASAL SAND, Bore - Basal Sand West	SWL only. 251_QAQCD05 Taken- No.	25.40
SDB05A	5-Mar-2025 10:02:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	26.87
SDB05B	5-Mar-2025 09:50:00	GROUNDWATER - CODISPOSAL	Insufficient water to pump. Unsuccessful bailing attempts. Insufficient water to bail. Tape stopped at bottom of bore at 41.12m but keeps sinking until 42.10m. No sample collected.	40.97
SDB06A	4-Mar-2025 11:37:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Bailer. Not turbid. Clear colour. Slight organic odour. No particles. (Earthy Odour). Insufficient water to pump. Bailed 12L then sampled.	28.85
SDB06B	5-Mar-2025 10:38:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	36.03
SDB07A	4-Mar-2025 14:03:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	18.37
SDB07B	4-Mar-2025 12:51:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. pH double checked and confirmed. EC double checked and confirmed.	17.96
SDB08A	5-Mar-2025 08:01:00	GROUNDWATER - CODISPOSAL, Bore - Basalt East	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles.	25.87
SDB08B	5-Mar-2025 06:42:00	GROUNDWATER - CODISPOSAL	Low Flow Pump. Not turbid. Clear colour. Organic odour. No particles. (Earthy odour). SWL double checked and confirmed.	28.12
T1	5-Mar-2025 10:50:00	GROUNDWATER - CODISPOSAL, Bore - Tertiary Basalt	Low Flow Pump. Not turbid. Clear colour. Nil odour. No particles. EC double checked and confirmed.	24.75